


HOW TO SUCCEED

Cheyenne County Landfill
From Marginal To Outstanding



- General Notes:**
1. Contours represent existing ground elevations.
 2. The location of MSW #1, 2, 3, 4, 5, and 6 are based on location provided to the landfill operator and represent the best information provided at the time.
 3. See Sheet No. 2 for miscellaneous details.
 4. POT #1 - Point of Interest of Department area (fill-in)

LEGEND

See "S" Notes on Sheet 2 of this set	●
See "B" Notes on Sheet 2 of this set	○
Electrical Station, No. Inside Closure, Center of Station	△
See Site Plan	---
Boundary Line	---
Existing Right of Way Line	---
Delimited Right of Way Line	---
Existing Right of Way Line	---
Proposed Line	---
Original Government Survey	(1840)
Point of Closure	PC
Point of Curve	PC
Point of Tangency	PT
Benchmark	(3 B.M.)
Abandonment Point	(1-1999)
Site Abandonment Area	② (2007)
Completed Abandonment	③ (2011)



Facility Site Map
 Cheyenne County Solid Waste
 Landfill Facility
 Cheyenne County, Kansas

PENCO ENGINEERING, P.A.
 P.O. BOX 362
 HUNTSVILLE, KY 40332
 (781) 244-4411

DESIGNED BY: DKO	CHECKED BY: PCT	DATE: 11/20/13
DRAWN BY: DKO	DATE: 11/20/13	SCALE: AS SHOWN
PROJECT NO.: 13-001	DATE: 11/20/13	4 OF 26

1: 11/20/2013 10:57:10 AM 10/20/2013 Cheyenne County Solid Waste Landfill Facility 13-001 13-001-01



07/28/2010



07/28/2010



07/28/2010



07/28/2010







01/10/2012

h. Respondent operated its Landfill in violation of rules and regulations

b. Respondent operated its Landfill in violation of rules and regulations
of the Secretary, to wit:

i. Respondent failed to place waste in a manner that achieves
mass stability provided in all phases of operation in violation of
K.A.R. 28-29-108(n)(1). **Penalty:** [REDACTED]

ii. Respondent failed to apply at least six inches of daily cover or
alternate daily cover (ADC) to all exposed waste by the end of
each working day in violation of K.A.R. 28-29-108(b). **Seventh
Offense. Penalty:** [REDACTED]

iii. Respondent failed to compact waste to the highest practical
density in violation of K.A.R. 28-29-108(m)(2). **Second
Offense. Penalty:** [REDACTED]

iv. Respondent failed to maintain the size and slope of the working
face so that the working face is no larger than necessary to
conduct operations in a safe and efficient manner in violation
of K.A.R. 28-29-108(o)(1). **Third Offense. Penalty:** [REDACTED]

County Commissioners Got Involved

- Hired new operator
- Bought additional equipment
- Met with BWM several times
- Visited the landfill several times



05.22.2013 10:35





CAUTION

STOP
CHEMICAL
STORAGE
AREA





05.22.2013 10:32

Byron's Road Map:

- Protect Groundwater
- Manage Storm Water
- Prevent Nuisance

Protect Groundwater

- Keep Working Face Small
- Apply Daily Cover
- Apply Intermediate Cover

Manage Storm Water

- Prevent Run on & Runoff
- Minimize Contact Water
- Contain Contact Water



05.22.2013 10:34



12.03.2013



05.22.2013 10:32















First Lift





