

**DIVISION OF ENVIRONMENT
QUALITY MANAGEMENT PLAN**

PART II:

**BUREAU OF WATER
QUALITY ASSURANCE MANAGEMENT PLAN**

Revision 7
12/22/08

Kansas Department of Health and Environment
Division of Environment
Bureau of Water
1000 SW Jackson St., Suite 420
Topeka, Kansas 66612-1367

TABLE OF CONTENTS

<u>Section</u>		<u>Revision</u> <u>No.</u>	<u>Date</u>
0	SIGNATURES/APPROVAL	7	12/22/08
1	INTRODUCTION	6	11/01/07
	1.1 Purpose of Document.....	2	11/01/07
	1.2 Historical Background	4	11/01/07
	1.3 Current Quality Assurance Objectives.....	2	11/01/07
2	BUREAU DESCRIPTION	6	12/22/08
	2.1 Mission Statement.....	3	11/01/07
	2.2 Historical Overview	5	12/22/08
	2.3 Contemporary Goals.	3	11/01/07
	2.4 Organization and Responsibilities	4	12/22/08
3	QUALITY ASSURANCE POLICIES	3	12/22/08
	3.1 General Bureau Policies.....	3	12/22/08
	3.2 Activities Subject to Policies.	3	12/22/08
4	QUALITY ASSURANCE ORGANIZATION	2	11/01/07
	4.1 Role of Bureau Director.....	2	11/01/07
	4.2 Role of Bureau QA Representative.....	3	11/01/07
	4.3 Role of Section Chiefs	4	12/22/08
	4.4 Role of Program Managers	2	11/01/07
	4.5 Staff Responsibilities.	2	11/01/07
5	INTRAMURAL QUALITY ASSURANCE DOCUMENTATION	2	11/01/07
	5.1 Quality Assurance Project Plans.....	2	11/01/07

TABLE OF CONTENTS
(CONTINUED)

<u>Section</u>	<u>Revision</u>	<u>Date</u>
	<u>No.</u>	
5.2 Sample Chain of Custody	2	11/01/07
5.3 Data Custody, Management and Reporting	2	11/01/07
5.4 Standard Operating Procedures.....	2	11/01/07
5.5 Implementation Requirements	2	11/01/07
6 EXTRAMURAL QUALITY ASSURANCE DOCUMENTATION	2	11/01/07
6.1 Minimum Expectations for Contractors.....	2	11/01/07
6.2 Minimum Expectations for Regulated Facilities	2	11/01/07
7 MONITORING SITE SELECTION/DOCUMENTATION	3	12/22/08
7.1 Minimum Siting Requirements.....	3	12/22/08
7.2 Documentation of Geographical Location.....	2	11/01/07
7.3 Narrative Description and Photographic Documentation	3	11/01/07
8 EQUIPMENT AND SUPPLIES.....	2	12/22/08
8.1 Procurement/Inventory Requirements	2	11/01/07
8.2 Equipment Maintenance/Calibration Requirements	2	11/01/07
8.3 Equipment Repair and Replacement Guidelines	2	11/01/07
8.4 Backup Requirements for Critical Equipment.....	2	11/01/07
9 QUALITY ASSURANCE PROGRAM EVALUATION	3	12/22/08
9.1 Internal Review	3	12/22/08

TABLE OF CONTENTS
(CONTINUED)

<u>Section</u>	Revision <u>No.</u>	<u>Date</u>
9.2 Independent Audits	3	12/22/08
9.3 Staff/Supervisor Performance	3	12/22/08
9.4 Annual Program Evaluations.	3	12/22/08
10 RESOURCES AND TRAINING	3	11/01/07
10.1 Supervisory Expectations.....	2	11/01/07
10.2 Continuing Educational Opportunities	3	11/01/07
10.3 New Employee Orientation.....	2	11/01/07
10.4 Safety Considerations	2	11/01/07
11 COMPUTER TECHNOLOGY	2	11/01/07
11.1 Computer Hardware and Software.....	2	11/01/07
11.2 Data Entry Requirements	2	11/01/07
11.3 Verification of Calculations	2	11/01/07
12 REVIEW AND REVISION OF QUALITY ASSURANCE MANAGEMENT PLAN	3	12/22/08

SIGNATURES/APPROVALS

Industrial Programs Section:

(Signature, Section Chief)

(Date)

Municipal Programs Section:

(Signature, Section Chief)

(Date)

Watershed Management Section:

(Signature, Section Chief)

(Date)

Public Water Supply Section:

(Signature, Section Chief)

(Date)

Livestock Waste Management Section:

(Signature, Section Chief)

(Date)

Technical Services Section:

(Signature, Section Chief)

(Date)

Geology Section:

(Signature, Section Chief)

(Date)

Watershed Planning Section:

(Signature, Section Chief)

(Date)

Administration & Finance Section:

(Signature, Section Chief)

(Date)

Bureau of Water:

(Signature, Bureau Director)

(Date)

Division of Environment
Quality Assurance Officer:

(Signature, QA Officer)

(Date)

Division of Environment:

(Signature, Director)

(Date)

Section 1

INTRODUCTION

1.1 Purpose of Document

This document represents the Bureau of Water's (BOW's) contribution to Part II of the Division of Environment Quality Management Plan or "QMP." It establishes quality assurance (QA) goals, policies, procedures, organizational responsibilities, and program evaluation and annual reporting requirements applicable to all environmental monitoring programs administered by BOW. The document also serves as a foundation for the Bureau's program-level QA management plans presented in Part III of the QMP.

1.2 Historical Background

The Division of Environment began development of a comprehensive quality management plan in 1983. This document served as a standard for the Bureau of Water as well as other bureaus. The document was approved by the Environmental Protection Agency (EPA) on February 6, 1984 and served as the Bureau's quality assurance document. It became apparent that the old document with its shortcomings was no longer adequate, especially in light of the many and varied types of sampling required by new water supply and wastewater regulations. The next major revision to all parts of the QMP was completed in July, 1995 and approved by EPA. Part I of the QMP was again revised in December 2004 and approved by EPA for a five-year period. This update of the Bureau of Water Part II QMP was prepared under the auspices of the Part I QMP (December 2004) after EPA review and approval.

1.3 Current Quality Assurance Objectives

The objective of the QMP is to ensure that all environmental monitoring programs within the Bureau produce data of known and acceptable quality and support, in a scientifically defensible manner, the informational needs and regulatory functions of the Kansas Department of Health and Environment (KDHE).

Section 2

GENERAL BUREAU DESCRIPTION

2.1 Mission Statement

The explicit mission of BOW is "to protect and improve the health and environment of Kansans through wise regulation of waters of the state."

2.2 Historical Overview

In 1885, the Kansas Board of Health was created. In 1907, water supply and pollution control legislation was passed. The agency at that time was the Kansas Board of Health and the operating department was called the Division of Sanitation and was based in Lawrence. Later, the Division was named Division of Environmental Health Services and included water supply and wastewater treatment, occupational health and radiation, air quality and general sanitation (including solid wastes). In 1974 the agency went from a board structure to a cabinet level department and was renamed the Kansas Department of Health and Environment. The new agency was divided into two main divisions and some support divisions. The Division of Environment was set up with a bureau for water programs, air programs, solid and hazardous waste, general sanitation, and radiation.

The water bureau was originally known as the Bureau of Water Protection and had public water supply, water pollution control and water quality monitoring sections. The Bureau has been reorganized many times in the ensuing years and now has nine sections: Industrial Programs, Municipal Programs, Watershed Management, Technical Services, Livestock Waste Management, Public Water Supply, Geology, Watershed Planning, and Administration. The Technical Services Section was the parent section of BOW field staff until the Bureau of District Operations, now BEFS, was formed in 1993.

2.3 Contemporary Goals

- (1) Greater than 95% of the population served by community water systems will receive water meeting standards.
- (2) Rivers and lakes will support their identified use including healthy communities of fish, plants, and other aquatic life, and use for recreation and drinking water supply. Groundwater quality will be protected.

2.4 Organization and Responsibilities

Figures 2.4-1 depicts the organizational structure of BOW; Table 2.4-2 illustrates Bureau and section level work responsibilities.

Figure 2.4-1 Bureau of Water Organizational Structure

See http://kdhenet/human_resources/org_chart/ENVIR/BOW/BOW.pdf

TABLE 2.4-1
 KANSAS DEPARTMENT OF HEALTH AND ENVIRONMENT
 BUREAU OF WATER - KARL MUELDENER

FINANCE & ADMINISTRATIVE SECTION

SRF Administration
 Clean Water & Public Water Supply SRF
 Payments/Repayments
 KDFA Coordination

Administrative Services
 Bureau Budget Preparation
 Accounts/Records
 Cash Flow Projections
 Grants Administration
 Building Services
 Program Support
 Time Accounting

#MUNICIPAL PROGRAMS SECTION

Engineering Unit
 Engineering Reports
 Plans & Specifications
 O&M Manuals
 Inspection/Operator Assistance
 Special Problem/Investigation
 Wastewater Minimum Standards of Design
 Construction Oversight
 Preconstruction/Final Inspection
 Program Support
 Clean Water - State Revolving Fund (CW-SRF) Project Engineering
 Sewer Extension Permits
 CDBG Block Grant Review

Permitting & Planning
 Project Planning
 Enforcement/Administrative Actions
 CW-SRF Priority System
 Record Keeping
 Program Support
 Coordination with KDFA
 Permitting, Wastewater

#ENVIRONMENTAL GEOLOGY SECTION

UIC (Class I, III, IV, V) Injection Wells
 LPG Storage
 Natural Gas Storage
 Permit Development
 Operator Support
 Environmental Geology Support
 Inspections
 Water Well Licensing
 Water Well Inspection
 Water Well Database

Technical Support
 Brine Spreading on public records

#PUBLIC WATER SUPPLY SECTION

Permits & Plan Review
 Water Supply Permits
 Water System Approval
 PWS Minimum Standards of Design
 Engineering Reports
 Plans & Specifications
 Water Supply Development
 PWS Needs Survey
 PWS Priority List
 SRF Program
 CDBG Block Grant Review
 Inspection/Operator Assistance
 Troubleshooting/Special Problems
 Capacity Development Program
 PWS-SRF Project Planning
 SRF-Engineering

Compliance/Data Management Unit
 PWS Monitoring & Compliance Tracking
 PWS Regulation Development
 Compliance Assistance & Training to PWS's
 PWS Database Development & Maintenance
 PWS Record File Management
 PWS Compliance, Violation & Enforcement Reports
 PWS Report & Sample Results Review
 PWS Statistical Reports
 EPA Liaison

#TECHNICAL SERVICES SECTION

Technical Support Unit
 Operator Cert
 Compliance/Renewal
 Technical Outreach Program (104g)
 104(b)(3) Grant Program
 KETS Liaison & Advisory
 Annual Operator School
 Correspondence Courses
 Certification Exams
 On-site Training
 Classroom Training
 Record Keeping
 Water Pollution Abatement
 Complaint/Investigation Asst.
 Emergency Coordination
 Municipal Sludge Program (503)

Interagency Hazard Mitigation Team
 Water Shortages
 Cross Connections
 Water/Sewer Technical Assistance
 In-House Training & Technical Assistance
 Management/Asst/Program Support
 EPA O&M Awards Program
 Liaison w/Bureau of Environmental Field Services

Permits & Compliance Unit
 Technical Permit Review
 NPDES & State Permit Issuance & Renewals
 Program Support
 Permits & Compliance System (PCS)
 Discharge Monitoring Review
 Laboratory Report Review
 Directives/Orders
 Legal Office Coordination
 Hearings
 EPA Liaison

Water Quality Standards Unit
 Triennial Reviews
 Permit Limit Development
 Permit Certification
 Criteria Research
 Procedures Development

#INDUSTRIAL PROGRAMS SECTION

Pretreatment Unit
 Develop Local Programs
 Monitor Local Programs
 Permit Development/Admin
 Monitor Industrial Compliance
 Enforcement/Administrative Actions
 Reg/Admin. Program Assistance
 Permit Coordination
 Program Support
 Pretreatment Program Technical Asst

Industrial Unit
 Minimum Standards of Design
 Engineering Reports
 Plans & Specifications
 Permit Development/Admin
 Enforcement/Administrative Actions
 Inspection/Operator Assistance
 Site Appraisals
 Special Problems/Investigation
 Stormwater Permitting
 Program Support

Industrial Stormwater Data/Support Unit
 Permit Development and Issuance
 Permit Administration
 Enforcement and Administrative Actions
 Outreach, Information and Education

#WATERSHED MANAGEMENT SECTION

Local Environmental Protection Unit
 LEPP Administration
 Grants
 Local Environmental Protection Plans
 Local Program Reviews
 Sanitary Code Review and Approval
 Administration of On-site Wastewater Regulations
 Technical Assistance
 Information and Education
 Consistency Certifications
 Source Water Assessment Program
 Federal Assistance and Development

Watershed/Water Quality Protection Unit
 KS Nonpoint Source Management Plan
 NPS Principles and Practices
 KS Catalog of NPS Pollution Control Practices
 Demonstration Projects
 Contract Administration
 Project Development
 Demonstration Project Financial Assistance
 Assessment and Analysis
 Water Quality
 GIS
 Water Supply Protection
 Watershed
 Wellhead
 Riparian Area Management
 Technology Development and Transfer
 Local Nonpoint Source Plan
 Environmental Coordination Act
 Section 404 Permit

#LIVESTOCK WASTE MANAGEMENT SECTION

Engineering Reports
 Plans & Specifications
 Minimum Standards of Design
 Permit Development
 Monitoring Reports
 Inspection/Operator Assistance
 Technical Support

#OFFICE OF WATERSHED PLANNING

Total Maximum Daily Loads

Section 3

QUALITY ASSURANCE POLICIES

3.1 General Bureau Policies

The Bureau relies on environmental monitoring data to support regulatory and administrative decisions. In addition, monitoring data is necessary for process control at water supply and wastewater treatment facilities, and for information necessary for enforcement actions. Therefore, efforts to document and improve the quality of monitoring and sampling data are extremely important. All monitoring and sampling activities performed within the Bureau (intramural) and by independent contractors and consultants (extramural) are expected to comply fully with the following policies:

- (1) The objectives and tolerable levels of data uncertainty of any environmental monitoring project shall be determined prior to the implementation of data collection activities. This determination shall be made in the planning stage of the project so that appropriate procedures will be incorporated into the project and the resulting data will meet stated objectives.
- (2) A QA program plan, describing how the activity will achieve the stated objectives, shall be developed by the project manager and approved by the appropriate Section Chief, and by the Bureau QA Officer prior to the initiation of data collection.
- (3) All QA and quality control (QC) measures shall be integrated into environmental monitoring programs in the most cost-effective manner possible without compromising data quality.
- (4) Sample collection and analysis activities and data management activities shall be subjected to periodic evaluation to identify and correct deficiencies and enhance the overall credibility of the Bureau's programs.
- (5) Measures shall be instituted to ensure that the quality of environmental monitoring data collected by the Bureau is carefully and permanently documented.

3.2 Activities Subject to Policies

The Bureau of Water administers several environmental sampling programs, but relies on the Bureau of Environmental Field Services (BEFS) for sampling activities. Data are routinely gathered on concentrations of contaminants in water, sludge and other media.

Drinking water program sampling categories can be broken down into compliance sampling and operational control. Compliance monitoring includes raw water, point of entry, distribution system, and plant samples. Samples for operational control include any samples collected for the purpose of determining or verifying chemical feed rates.

Wastewater program sampling categories can be broken down into compliance, operational control and pretreatment samples. Compliance samples include samples from the plant outfall, sludge samples, soil samples, synthetic membrane liner leak detection systems, groundwater, and stream samples. Samples for operational control include any samples collected for the purpose of determining or verifying various operational control parameters.

Pretreatment samples are those samples taken from the premises of an industrial discharger for the purpose of determining compliance with pretreatment ordinances and/or pretreatment permits.

The requirements of the QMP are applicable to all environmental monitoring and measurement activities performed within, or on behalf of, the Bureau. However, it is recognized that unusual or unprecedented emergency situations may require immediate responses based on best professional judgement of staff rather than the provisions of preapproved workplans or project plans. To the extent practicable, such responses should be based on established procedures and protocols.

Section 4

QUALITY ASSURANCE ORGANIZATION

4.1 Role of Bureau Director

The Bureau Director oversees the development, revision, and implementation of the bureau-level QA management plan. With the assistance of the Bureau QA Representative and Section Chiefs, the Bureau Director ensures that the requirements of the plans are fulfilled in the most cost-effective manner possible without sacrificing the quality of the environmental monitoring data. The Bureau Director prioritizes the training and continuing education needs of staff and develops funding proposals to accommodate these needs as necessary.

4.2 Role of Bureau QA Representative

The Bureau QA Representative is directly responsible for reviewing and approving quality assurance project plans (QAPPs) and standard operating procedures (SOPs) administered by the Bureau. The Bureau QA Representative also provides guidance to program/project managers involved in the preparation and implementation of these documents. The Bureau QA Representative operates under a degree of autonomy which allows independent assessment of QA performance and the need for corrective action. The Bureau QA Representative analyzes QA evaluation reports and related information submitted by Section Chiefs and Program/Project Managers. The Bureau QA Representative works with these staff and the Divisional QA officer in the resolution of identified QA problems and concerns.

4.3 Role of Section Chiefs

The Section Chiefs generally are responsible for more than one environmental monitoring program and may supervise other, frontline supervisors such as program managers and unit chiefs. They oversee the QA aspects of the environmental monitoring programs on a day-to-day basis, identify QC deficiencies within their respective programs, track the QC performance of staff, and assist in the periodic review and revision of the bureau-level and program-level QAPPs and SOPs. The Section Chiefs coordinate closely with their program managers to ensure that all QA and QC requirements are routinely implemented.

4.4 Role of the Program Managers

Program managers work closely with non-supervisory staff to ensure that the requirements of the program-level QA management plans and associated SOPs are implemented in a timely, consistent and reliable fashion. Together with the Section Chiefs, the program managers strive to improve the precision and accuracy of all environmental monitoring data through the effective day-to day allocation of staff and other resources. They also bring the QC training needs of staff to the attention of their Section Chiefs, develop program-level QAPPs and SOPs for new monitoring initiatives, and periodically review and revise existing QAPPs and SOPs to meet the evolving informational needs of the Bureau.

4.5 Staff Responsibilities

Staff directly involved in the collection and analysis of environmental monitoring data play an important role in the implementation of the Bureau QMP. The quality and usefulness of the data ultimately reflect the willingness of staff to abide by the SOPs and to participate constructively in the ongoing review and revision of the QAPPs and SOPs. Because they carry out the provisions of these plans and procedures on a routine basis they often develop an understanding of the technical strengths and weaknesses of the monitoring programs. Program managers and administrative staff are expected to solicit input from these employees when developing new or revised QAPPs or SOPs.

Section 5

INTRAMURAL QUALITY ASSURANCE DOCUMENTATION

5.1 Quality Assurance Project Plans

Intramural monitoring programs include all routine water monitoring programs and special studies performed by Bureau staff. Pursuant to Bureau policy, Quality Assurance Project Plans (QAPPs) must be developed by the manager of each program and approved by the Section Chief involved, and the Bureau QA Representative prior to initiation of data collection. All program-level QAPPs must be prepared using a standardized document control format in which the report section number, revision number, date of revision, and page number appear in the upper right-hand corner of each page. Program-level QAPPs shall contain the following elements unless the reviewing Bureau QA Representative determines that a given element falls outside the technical scope of the program/project:

- (1) title page identifying program/project, Bureau/office, division and agency;
- (2) approval page with blocks for appropriate signatures and dates;
- (3) table of contents, including a list of any appendices;
- (4) overview of program/project, including statement of purpose, developmental history, and any relevant statutory and regulatory requirements;
- (5) description (or chart) of organizational hierarchy with accompanying list of participating staff positions and statement of staff responsibilities;
- (6) description of data performance criteria expressed in terms of data precision, accuracy, completeness, comparability and representativeness for each parameter of interest;
- (7) description of, and rationale for, intended sampling frequency, sampling network design and monitoring site selection criteria;
- (8) description of sampling equipment and associated decontamination procedures (reference SOPs, as appropriate);
- (9) description of field procedures, including sample collection, analysis, preservation, transport and chain-of-custody procedures and accompanying safety protocols (reference SOPs, as appropriate);
- (10) list of laboratory parameters and sample holding times and accompanying description of laboratory analytical and safety protocols (note: SOPs adopted by the

Kansas Division of Laboratories or other cooperating laboratories may be adopted by reference, provided they contain the informational elements stipulated in section 5.4, below);

- (11) description of data validation, storage, transfer, reporting and backup requirements and any special documentation requirements (reference SOPs, as appropriate);
- (12) description of equipment testing, calibration and preventative maintenance procedures (reference SOPs, as appropriate);
- (13) description of inspection procedures and acceptance requirements for purchased equipment and supplies (reference SOPs, as appropriate);
- (14) description of procedures (including statistical procedures) used to evaluate data precision, accuracy, completeness, representativeness and comparability, including a detailed characterization of internal QC procedures and external performance audit requirements;
- (15) description of procedures used to evaluate and enhance utility of environmental monitoring data including, but not necessarily limited to, procedures and assumptions applied in the identification and treatment of (a) outliers and other anomalous data, (b) nonlinear data requiring statistical transformation, and (c) values reported as “less than” or “greater than” established reporting limits;
- (16) description of corrective action procedures for out-of-control situations;
- (17) description of procedures for determining the quality of ancillary data acquired from external sources not subject to the provisions of the divisional QMP (e.g., meteorological, hydrological, geological, chemical and/or biological data obtained from other state and federal agencies); and
- (18) description of program/project deliverables (electronic databases, summary statistics, illustrative materials, interim and final reports, etc.) and schedule for completion.

5.2 Sample Chain of Custody

Employees collecting and transferring samples to the Kansas Health and Environmental Laboratories for analysis shall complete a chain-of-custody form and submit the appropriate completed form, along with the samples, to appropriate laboratory personnel. Copies of sample submission forms shall be maintained in the custody of the program managers or their designees.

5.3 Data Custody, Management and Reporting

Bureau of Water and program-level QAPPs shall contain provisions which ensure the proper validation, transfer, storage and backup of environmental monitoring data. Data reporting procedures shall be specifically addressed within the QAPPs and/or the accompanying SOPs. Where practical, the plans shall provide mechanisms for reporting and permanently documenting the quantitative precision and accuracy of the data. At a minimum, all plans must contain provisions for reporting and documenting data completeness, representativeness and comparability in qualitative terms.

5.4 Standard Operating Procedures

Standard operating procedures document the protocols involved in the collection, preservation, transport, transfer and analysis of environmental samples and validation, storage/retrieval, transfer and backup of environmental data. These procedures are a critical component of all program-level QAPPs. They facilitate consistency among staff and provide a written record of the methods used to obtain and preserve environmental monitoring data. All SOPs are prepared according to a standardized written format, in which the report section number, revision number, date of revision, and page number appear in the upper right hand corner of each page, and are approved by the program manager and the Bureau QA Representative.

All SOPs must be scientifically rigorous and meet the precision and accuracy expectations of their respective program-level QAPPs. They must also be written in a clear and straightforward fashion so that they may be readily understood and implemented by all users. The SOPs augment information provided in the program-level QAPPs by providing the following information, where applicable:

- (1) title page with appropriate blocks for approval signatures/dates;
- (2) table of contents including a list of any appendices;
- (3) introductory statement describing intended application of SOP and providing overview of procedure;
- (4) statement of minimal technical qualifications for participating staff;

- (5) an inventory of applicable field, laboratory and safety equipment;
- (6) instructions for calibrating field instruments and performing associated troubleshooting procedures;
- (7) instructions for collecting, preserving and handling environmental samples and/or performing environmental measurements, emphasizing health and safety considerations and highlighting any steps requiring special attention, patience or care;
- (8) instructions for collecting and analyzing duplicate or replicate samples and for preparing field blanks, spikes and split samples, emphasizing health and safety considerations and highlighting any steps requiring special attention, patience or care;
- (9) instructions for preparing and analyzing samples in the field and performing related troubleshooting procedures, emphasizing health and safety considerations, steps requiring special attention, patience or care, and possible interferences jeopardizing data quality;
- (10) instructions for transporting, transferring and storing environmental samples and accompanying field data and records (e.g., notes, logs, photographs, audio tapes, audiovisual tapes), emphasizing chain-of-custody procedures, health and safety considerations, and steps requiring special attention, patience or care;
- (11) description of data acquisition, storage, retrieval, transfer, verification, backup and analysis procedures, long-term data/records management procedures, and enabling computer hardware and software;
- (12) glossary of technical terms and acronyms employed in SOP (often included as appendix); and
- (13) checklist of applicable field equipment and supplies (often included as appendix).

Quality assurance project plans for larger monitoring programs may contain several SOPs. Again, QAPPs may adopt previously existing SOPs by reference, provided the referenced SOPs meet the minimum informational requirements identified above.

5.5 Implementation Requirements

Environmental monitoring operations shall be implemented by qualified personnel based on approved QAPPs and SOPs. In the event of unforeseen contingencies, any deviation from approved

procedures shall be documented and reported by the program manager to the supervising Section Chief and Bureau QA Representative. The significance of the deviation, and any needed adjustments or corrective actions, shall be determined by the Section Chief and Bureau QA Representative with input from the program manager and non-supervisory staff actually performing the work. Staff and supervisory expectations in the event of a departure from approved procedures shall be addressed in the approved QAPP.

Section 6

EXTRAMURAL QUALITY ASSURANCE DOCUMENTATION

6.1 Minimum Expectations for Contractors

Outside entities engaged in environmental monitoring activities under contractual agreement with the Bureau must develop QAPPs and SOPs consistent with BOW QA/QC plans. These plans and SOPs must be approved by the program manager serving as technical advisor on the project, by the appropriate Section Chief and the Bureau QA Representative prior to the initiation of data collection activities. Contracts, workplans, and QAPPs must contain provisions which ensure that the contractor will prepare and submit the final project report to the Bureau within a prescribed time frame.

Quality assurance documents associated with contractual monitoring activities must be maintained in an up-to-date condition. Minor changes in the work performed under a contract, workplan, or QAPP must be reviewed and approved by the appropriate program manager and supervising Section Chief prior to implementation. Substantial revisions or addendums to the original documents must be reviewed and approved in the same manner as the original documents.

6.2 Minimum Expectations for Regulated Facilities

Municipal, industrial, and agricultural facilities regulated by the Bureau are often required to monitor contaminant releases into the environment. On occasion, they are required to perform more comprehensive pollutant transport, fate and environmental impact studies. Because these facilities are subject to specific federal statutes and regulations, binding generalizations regarding QA requirements are inappropriate. However, standardized QAPPs and accompanying SOPs shall be prepared in a format compatible with the Bureau QAPP for use by the regulated entity. These standardized plans shall be prepared by a designated program Manager and are subject to review by the supervising Section Chief, and Bureau QA Representative.

Section 7

MONITORING SITE SELECTION AND DOCUMENTATION

7.1 Minimum Siting Requirements

Sampling and monitoring sites must be selected to meet the following criteria: (1) representative samples, (2) reasonable access, (3) ability to document location, and (4) safety. The samples collected must be representative to be of any value; accordingly, the site must be chosen with this in mind at the outset. The sample collector must be able to collect samples at the site, safely. Information on the date, time and exact location of the sampling site is required by EPA and Kansas regulations; therefore, it is important that the sample collector be able to identify the site.

7.2 Documentation of Geographical Location

Criteria must be developed in each program or activity with regard to the accuracy of location of the sample site. For some purposes identification of the site may be adequate to the nearest ten acres; at most sites however, it is important to locate the site to within 50 or 100 feet. Various means exist for identification of the sampling site including global positioning system (GPS) location, legal descriptions, or reference to known sites which can be identified from maps. The criteria must be developed to meet Bureau QA/QC criteria and approved by the Project Manager, the appropriate Section Chief and the Bureau QA Representative.

7.3 Narrative Description and Photographic Documentation

In cases involving fishkills, contaminant spills, unauthorized discharges of pollutants or discharges where legal action may be necessary, it is imperative that the sample and sampling site be documented correctly, and coordination of sampling efforts with BEFS be undertaken. A narrative description of the sampling site along with other facts about the site must be recorded. Photographic documentation shall accompany the narrative whenever possible. Form 7.3-1, below, shall be used for narrative and photographic documentation purposes. In cases where digital photographs are utilized, Form 7.3-1 may be modified to incorporate the digital photographs. Any modified form shall include all information fields on Form 7.3-1.


**KANSAS DEPARTMENT OF HEALTH AND ENVIRONMENT
DIVISION OF ENVIRONMENT**

**Bureau of Water
Form 7.3-1 Photo Mounting Sheet**

Name of Site: _____ **Legal:** _____ **Permit:** _____
Location: _____ **County:** _____ **By:** _____
Date: _____ **Time:** _____ **Type of camera:** _____ **Weather Condition:** _____



Picture #:
General Direct. Facing:
Comments: _____



Picture #:
General Direct. Facing:
Comments: _____

Section 8

EQUIPMENT AND SUPPLIES

8.1 Procurement and Inventory Requirements

The Bureau and program QA/QC documents shall establish requirements for equipment procurement and inventory requirements. This policy shall conform with KDHE guidelines when applicable. Program managers and Section Chiefs shall be responsible for following purchasing and inventory guidelines.

8.2 Equipment Maintenance and Calibration Requirements

Equipment maintenance and calibration requirements shall be the responsibility of the program manager and/or the Section Chief. Guidelines for equipment maintenance and calibration shall be documented in the Bureau's SOPs.

8.3 Equipment Repair and Replacement Guidelines

Generally, broken or unserviceable equipment should be repaired if possible. Factors which influence repair decisions include remaining expected life, cost of repair, and degree of obsolescence of the equipment. Guidelines for repair or replacement shall be developed for inclusion in the program QA/QC document and shall be the responsibility of program managers and/or Section Chiefs.

8.4 Backup Requirements for Critical Equipment

Requirements for backup equipment shall be developed for inclusion in the program QA/QC document. Requirements for periodic exercising of standby equipment shall be developed and assigned to appropriate program managers and Section Chiefs.

Section 9

QUALITY ASSURANCE PROGRAM EVALUATION

9.1 Internal Review

All QA/QC aspects of Bureau environmental monitoring programs are subject to ongoing review by the program managers and Section Chiefs. Program managers are expected to cooperate fully with administrative requests for information on data precision/accuracy and overall QC performance. Section Chiefs are expected to track the QC performance of program managers, assist managers in identifying QC deficiencies within their programs, and facilitate the initiation of necessary corrective actions. The results of internal reviews conducted by the Section Chiefs are reported to the Bureau QA Representative, Bureau Director and Divisional QA Officer as part of the annual program evaluations.

Internal audits may also be performed by Bureau staff as needed. The audits may cover such items as the adequacy of physical facilities, equipment, personnel, training, field and laboratory procedures, record keeping, data validation and management, and other aspects of monitoring programs and will typically be completed by Program Managers, Section Chiefs, Bureau QA Representative, or Bureau Director.

9.2 Independent Audits

To enhance the quality and credibility of the environmental data gathered by BOW staff all monitoring programs are required to participate in QA audits performed by an independent party, such as EPA, or other public agencies or private consulting companies having prior experience and demonstrable expertise in program evaluations, and that are approved by the Division Director. Audit findings and corrective actions implemented in response to such findings, are reported to the Bureau Director and Divisional QA Officer as part of the annual program evaluations described in section 9.4.

9.3 Staff/Supervisor Performance

Position descriptions and performance evaluations are expected to accurately reflect the QA/QC functions and performance of the staff. All staff involved in environmental monitoring activities are expected to carry out their responsibilities under the QMP to the best of their abilities. Administration staff and program managers are expected to foster an appreciation for the role of QA/QC among nonsupervisory employees. In turn, the opinions and insights of nonsupervisory employees are to be taken seriously by program managers and administrative staff. The quality and credibility of the Bureau's environmental monitoring efforts ultimately depend on the willingness of all employees to work as a team, learn from their mistakes, and perform their duties in a diligent manner.

9.4 Annual Program Evaluations

End-of-year program evaluations are conducted by the Section Chiefs and the results submitted, in writing, through the Bureau QA Representative and the Bureau Director to the Divisional QA Officer by February 15 of the following year. The reports must indicate when, how, and by whom the evaluation was conducted, the specific aspects of the programs subjected to review, a summary of important findings, and technical recommendations for necessary corrective actions. Section Chiefs are expected to discuss the findings of the evaluations with the program managers and all participating field, laboratory, and data management staff.

Section 10

RESOURCES AND TRAINING

10.1 Supervisory Expectations

The quality of the environmental monitoring data gathered by BOW is strongly influenced by the level of staff training, experience and preparation. The Bureau QA Representative will work with the Section Chiefs and Program Managers to address the training needs of staff. To broaden the experience level of staff, supervisors also are expected to provide occasional opportunities for any interested employee to participate in activities outside his/her daily work routine (e.g., interprogram cross-training opportunities). Such activities must be within the general scope of the employee's classification specifications and conform to the orientation and safety training requirements presented in sections 10.3 and 10.4, below.

10.2 Continuing Education Opportunities

Methods employed in the collection and analysis of environmental data are subject to continual refinement. Occasional conceptual or technological breakthroughs (e.g., satellite-based global positioning technologies; geographical information systems) may rapidly antique existing SOPs and require extensive training or retraining on the part of staff. Continuing education courses offered by some colleges or vocation educational institutions may fulfill these training needs. Staff participating in such courses may be reimbursed by the Division provided the subject matter is within the general scope of the employees' position descriptions, funds for training have been set aside within the budget of the beneficiary program, and participation is otherwise allowable under prevailing agency training and travel policies.

10.3 New Employee Orientation

Supervisors, including program managers, shall ensure that all new employees, or recent transfers from other programs, or cross trainees receive a thorough indoctrination into the QA policies and procedures of the division, office and program. Part I of the QMP, together with the present document and applicable program-level QAPPs and SOPs, shall be required reading on the part of all new employees. After reading these documents, each employee shall sign an affidavit indicating that he/she has read the appropriate QA documentation. The signed affidavit shall be routed through the immediate supervisor and the Bureau QA Representative to the Division QA Officer. Apart from QA considerations, supervisors shall ensure that new employees participate in orientation seminars offered by the KDHE Personnel Office. Where appropriate, supervisory seminars offered by the Department of Administration shall be included in the training curriculum. The Bureau QA Representative will monitor compliance with new employee orientation and training requirements.

Critical safety procedures shall be thoroughly reviewed before any new employee engages in a potentially hazardous field or laboratory duty. New employees must demonstrate a satisfactory

understanding of safety considerations before they are required (or permitted) by their supervisors to participate independently in any potentially hazardous activity (see section 10.4, below).

All employees participating in environmental monitoring activities shall review Part I of the QMP, this document, and applicable program-level QAPPs and SOPs at least once each year. Upon completion of this review, each employee shall sign an affidavit indicating that he/she has read the appropriate QA documentation. The signed affidavit shall be routed through the immediate supervisor, the Section Chief, and the Bureau QA Representative to the Division QA Officer. This document review requirement shall be incorporated into the employee's written job expectations and factored by the immediate supervisor into the employee's annual performance evaluation.

10.4 Safety Considerations

Field and laboratory staff that participate in environmental monitoring programs encounter potentially hazardous situations on a frequent basis. In addition to the routine possibility of automobile, boating or equipment accidents, employees may encounter slippery surfaces, toxic substances, fire or electrocution hazards, infectious microorganisms, vicious animals, belligerent persons, or other threatening situations. Injuries or illnesses resulting from such situations may lead to substantial human suffering and, from a QA/QC perspective, deprive monitoring programs of the services of a valuable employee for an extended period of time.

Although it is not possible to predict every conceivable risk that may arise during the course of work, supervisors must ensure that those risks faced by staff on a recurring basis are addressed in the SOPs and are discussed during employee training. No employee shall be compelled by any supervisor (or coworker) to operate automobiles, boats or equipment that are known to be defective and unsafe. No employee shall be compelled by any supervisor (or coworker) to perform unusual or hazardous physical activities that are beyond the scope of the employee's position description. Rather, the supervisor shall consult with higher administrative staff to confirm whether the work or action is necessary and identify the appropriate employee (or outside consultant) for the task.

Field and laboratory staff are expected to abide by the safety protocols contained within the QAPPs and SOPs and to integrate safety considerations into all aspects of their work. To the extent possible, BOW shall routinely budget for ongoing safety training expenses (e.g., cardiopulmonary resuscitation and first aid training fees). Nonsupervisory employees are expected to bring potentially unsafe practices or situations to the attention of their program manager. In turn, the program manager shall evaluate the practice or situation and either take the appropriate corrective action or, in complicated circumstances, seek the advice of the Section Chief or higher level supervisor. Major corrective actions (those warranting changes in an SOP) shall be implemented by staff only upon approval of the Section Chief, and the Bureau QA Representative

Section 11

COMPUTER TECHNOLOGY

11.1 Computer Hardware and Software

All purchases of computer hardware and software must be approved in advance by the KDHE Office of Information Systems (OIS) and abide by Division purchasing requirements. Anti-virus software approved by OIS shall be installed and utilized on all Bureau lap-top and desktop computers used for storage, retrieval, exchange, backup and/or analysis of environmental data.

11.2 Data Entry Requirements

Environmental data (and metadata) manually entered into a state or federal computer database shall be examined and verified by at least one other Bureau employee familiar with the database. This process shall entail the selection of a representative, randomly selected sample of data and the documentation and correction of any data entry errors. The percentage of data subjected to review, the method of review, and the reviewer shall be specified in the approved QAPP. Staff transferring data electronically shall perform random spot checks of the transferred data and report any problems to OIS (or the external cooperating entity) for further investigation and resolution. Persistent or recurring problems also shall be reported to appropriate supervisory staff and the Bureau QA Representative for determination of necessary corrective actions. Such problems shall be addressed in the end-of-year program/project evaluation reports.

11.3 Verification of Calculations

Computer-based mathematical, statistical, geographical and graphical programs and models involving environmental data shall be tested before application and periodically thereafter. The reliability of software for performing calculations shall be tested by comparison to other computer programs, through hand calculations involving randomly selected data, or through other appropriate means. The reliability of computer-based calculations shall be verified according to schedules established in applicable QAPPs and whenever a problem is reported within the computational system. Quality assurance project plans shall describe the types of computer-based calculations to be performed and prescribe measures for monitoring the precision and accuracy of these calculations. This requirement may be waived in writing by the Bureau Director for specific applications involving commercial software after review by the Bureau Director and Bureau QA Representative. Originals of these waivers shall be retained by the Bureau QA Representative with a copy forwarded to the Divisional QA Officer.

Section 12

REVIEW AND REVISION OF QUALITY ASSURANCE MANAGEMENT PLAN

To ensure that the BOW QA management program continues to meet the highest scientific and organizational standards and remains consistent with the objectives established in section 1.3 of this document, all QA/QC documentation must undergo periodic review and revision. At yearly intervals, the Bureau QA Representative with input from the Director of the BOW shall review the bureau-level QA management plan, formulate necessary revisions, and obtain concurrences from the Divisional QA Officer and Division Director. Similarly, Program Managers shall review the program-level QAPPs and SOPs, formulate necessary revisions, and obtain concurrences from the supervising Section Chief and Bureau QA Representative. Minor changes to Part II can be made at any time and approved by the Bureau QA Representative and the Bureau Director.

The above activities normally will occur following the completion and submission of the annual program evaluations in February (see section 9.4). However, revisions to the office- and program-level QAPPs and SOPs may be initiated at any time, based on urgency of need or employee workload considerations. The Bureau of Water shall maintain in its library an updated hard copy of Part I of the QMP, along with this document and all program-level QA management plans and SOPs developed, implemented or administered by BOW staff. The Bureau QA representative will maintain an electronic representation of the BOW QMP Parts II and III on the KDHE internet server in a PDF "read only" format and made accessible to any interested employee or outside party.