



"Burke, Annie"
<BURKEA@KOCHIND.COM>

08/19/2005 11:32 AM

To "LeRock, Gary" <lerockg@KOCHIND.COM>, "Ellingson, Stephen" <Steve.Ellingson@KOCHIND.COM>, "Clay, Don" <ClayD@KOCHIND.COM>, "WBrady@GeoSyntec.com"

cc

bcc

Subject FW: Agenda for meeting on Friday, August 26, and List of Concerns /Issues

History: This message has been forwarded.

FYI. Andrea also left me a voice message. It appears that she is getting pressure to interact on some issues -- Don's e-mail yesterday indicate that Art believes that is what had been happening, my e-mail indicted that (until today) it had not been happening.

At least, we now have two areas where there are concerns (although we do not yet know why) as described in her recommendations under 2.2.

Before I get back with her, let's share some ideas on our response to her.

AnnieLaurie Burke, PE
Environmental Compliance Leader
KOCH Nitrogen Company
11559 US Highway 50
P.O. Box 1337
Dodge City, KS 67801
(620)227-8631 x350 (voice)
(620)227-6016 (fax)
(620)339-9024 (mobile)

-----Original Message-----

From: Stone.AndreaR@epamail.epa.gov [mailto:Stone.AndreaR@epamail.epa.gov]
Sent: Friday, August 19, 2005 10:59 AM
To: Burke, Annie
Cc: Toensing.Donald@epamail.epa.gov; Rohrman.Wray@epamail.epa.gov; mkamal@kdhe.state.ks.us; kdunn@kdhe.state.ks.us; espellma@kdhe.state.ks.us
Subject: Agenda for meeting on Friday, August 26, and List of Concerns/Issues

AnnieLaurie:

I have reviewed Koch's proposed Agenda and offer the following suggestions/changes/additions:

2.1. Identify Areas of Agreement/Disagreement - EPA is certainly willing to have a discussion on this, however, some details will probably need to be discussed later, since EPA and KDHE are not finished with our detailed review of the FSP and QAPP, and we are in the process of developing detailed comments.

RCRA



520261

I would like to add a subsection under Agenda Item #2

2.2 Define EPA Expectations:

A. Discussion on defining the vertical and horizontal extent of contamination

B. Discussion on the Scope of Work for the RFI Work Plan contained in the Part II of the Permit

Subsection 2.3 Optimize Communication - EPA would like additional clarification of this topic.

List of EPA Concerns:

1. Groundwater Investigation;
2. Analytical methods proposed for Soil investigation (SPLP and not Totals);
3. Using 20 times the SPLP result to determine list of analytes to sample for;
4. Focusing on Risk instead of defining the vertical and horizontal extent of contamination;
5. Plan lacks sufficient detail and uses generalizations.

Let me know if you have any questions regarding this e-mail.

Thanks!

Andrea R. Stone
U.S. EPA Region 7
901 North 5th Street
Kansas City, Kansas 66101

Phone: (913) 551-7662
Toll-Free 1-800-223-0425; x7662 (Only valid within MO, KS, NE & IA)
Fax: (913) 551-7947

stone.andrear@epa.gov