

Appendix N
EDR Leaking Underground Storage Tank
Report, December 2003



The EDR Radius Map™ Report

**North Industrial Corridor
North Industrial Corridor
Wichita, KS 67219**

Inquiry Number: 01103327.1r

December 22, 2003

***The Source
For Environmental
Risk Management
Data***

3530 Post Road
Southport, Connecticut 06890

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
Executive Summary.....	ES1
Overview Map.....	2
Detail Map.....	3
Map Findings Summary.....	4
Map Findings.....	5
Orphan Summary.....	76
Government Records Searched/Data Currency Tracking.....	GR-1

GEOCHECK ADDENDUM

GeoCheck - Not Requested

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer

Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL EDR BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.

Entire contents copyright 2003 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and the edr logos are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc. (EDR). The report meets the government records search requirements of ASTM Standard Practice for Environmental Site Assessments, E 1527-00. Search distances are per ASTM standard or custom distances requested by the user.

TARGET PROPERTY INFORMATION

ADDRESS

NORTH INDUSTRIAL CORRIDOR
WICHITA, KS 67219

COORDINATES

Latitude (North): 37.730200 - 37° 43' 48.7"
Longitude (West): 97.331000 - 97° 19' 51.6"
Universal Transverse Mercator: Zone 14
UTM X (Meters): 647077.9
UTM Y (Meters): 4176987.0
Elevation: 1310 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property: 37097-F3 WICHITA EAST, KS
Source: USGS 7.5 min quad index

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the ASTM E 1527-00 search radius around the target property for the following databases:

FEDERAL ASTM SUPPLEMENTAL

US BROWNFIELDS..... A Listing of Brownfields Sites

BROWNFIELDS DATABASES

US BROWNFIELDS..... A Listing of Brownfields Sites

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified.

EXECUTIVE SUMMARY

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STATE ASTM STANDARD

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Kansas Department of Environmental Protection's LUST Incident Report.

A review of the LUST list, as provided by EDR, and dated 11/04/2003 has revealed that there are 192 LUST sites within approximately 3 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
COPELAND TRUCKING, WICHITA	2655 N BROADWAY	1/4 - 1/2W	2	5
WICHITA SERVICE CENTER	1021 EAST 26TH STREET N	1/4 - 1/2ENE	A3	5
KANSAS METALS CO.	2829 N EMPORIA	1/4 - 1/2NNW	4	6
SPECIALIZED TRANSPORT SERVICE	2614 N MARKET	1/4 - 1/2W	5	6
EXCELL CORPORATION	2901 N MEAD	1/4 - 1/2NNE	7	7
BROWNING FERRIS INDUSTRIES	2745 NORTH OHIO STREET	1/4 - 1/2ENE	8	7
COMPRESSED GAS INC	602 E 29TH ST N	1/2 - 1 N	11	8
DOLE-AIROLDI (VACANT PROP)	2957 N BROADWAY	1/2 - 1 NNW	12	8
KAMEN (OLD EXCELL PLANT)	900 E 21ST	1/2 - 1 SSE	C15	9
NATIONAL BY-PRODUCTS	2155 N MOSLEY	1/2 - 1 SSE	C18	10
UNIVERSAL QUICKMART #11	2950 N OHIO	1/2 - 1 NE	F23	12
GARDEN WISE	1515 E 29 N	1/2 - 1 NE	F24	12
RAY'S ELECTRIC INC.	2934 FAIRVIEW	1/2 - 1 NW	25	13
HOLDERS REAL ESTATE,(ABANDONDE	620 W 24TH	1/2 - 1 WSW	26	13
Not reported	2645 NEW YORK AVE.	1/2 - 1 E	27	13
TOWN & COUNTRY #19 (TOTAL 1847	2600 N ARKANSAS	1/2 - 1 W	28	14
ROOF MECHANICS INC	3205 N BROADWAY	1/2 - 1 NNW	G31	15
WICHITA FIRE STATION #3	3261 N BROADWAY	1/2 - 1 NNW	G32	15
SHOP-A-LOT	621 W 21ST	1/2 - 1 SW	33	15
NATIONAL BY-PRODUCTS	518 E 18TH ST.	1/2 - 1 S	34	16
PURINA MILLS INC	414 E 18TH	1/2 - 1 S	35	16
BOBS TRANSMISSION INC	1900 N BROADWAY	1/2 - 1 SSW	H36	16
WICHITA, CITY OF	1901 N MARKET	1/2 - 1 SSW	H37	17
ALLEN'S CONCRETE	1820 N MOSLEY	1 - 2 S	38	17
MCBRIDE DEHMER CONSTRUCTION	2855 WOODLAND	1 - 2 WNW	40	18
AMOCO #2148	2001 E. 21ST ST.	1 - 2 ESE	I41	18
WHITESTAR	3223 N HYDRAULIC	1 - 2 ENE	J42	18
COASTAL MART #9180	2102 E 21ST	1 - 2 ESE	I46	20
HOME OIL CO INC	3511 NORTH OHIO	1 - 2 NNE	48	20
H & M CORNER STORE	2157 E 21ST	1 - 2 ESE	L49	21
INSTITUTE OF LOGOPEDICS	2400 JARDINE	1 - 2 ESE	50	21
KMVR RADIO TRANSMITTER	2829 SALINA	1 - 2 WNW	51	21
ARKANSAS AVE ELEMENTARY	3361 ARKANSAS	1 - 2 NW	52	22
WILLIAMS & SONS, WICHITA	2203 E 21ST	1 - 2 ESE	L53	22

EXECUTIVE SUMMARY

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
SALVATION ARMY	3601 N ST FRANCIS	1 - 2 N	M54	22
JAY CARLLEY, INC.	3615 N EMPORIA	1 - 2 N	M56	23
SMALL BUSINESS ADMIN	1325 W 29TH ST N	1 - 2 WNW	59	24
COLEMAN CO INC NORTHEAST THE	3600 N HYDRAULIC	1 - 2 NNE	N61	25
BUCKELY ROOFING CO	3601 N HYDRAULIC	1 - 2 NNE	N62	25
USD 259, MUELLER	2821 E 24TH ST. N.	1 - 2 E	63	25
AMERICAN PRIDE CAR WASH	1618 W 21ST	1 - 2 WSW	64	26
LOVE BOX CO INC	700 E 37TH ST N	1 - 2 N	65	26
YORK UNITARY PRODUCTS GROUP	801 E 37TH ST N	1 - 2 N	66	27
ROCK MOTOR COURT	3801 N BROADWAY	1 - 2 N	68	28
H J BORN STONE	901 W 35TH ST	1 - 2 NW	69	28
Not reported	200 W 37TH ST N	1 - 2 NNW	70	28
ISELY ALTERNATIVE SCHOOL	2500 E 18TH	1 - 2 SE	71	29
21ST & MAPLEWOOD CONTAM, WICHI	21ST / MAPLEWOOD	1 - 2 ESE	72	29
MEL HAMBELTON FORD INC.	3901 N BROADWAY	1 - 2 N	O73	29
WICHITA PUBLIC WORKS, NE STATI	2901 E 33RD ST N	1 - 2 NE	75	30
T & E OIL #11	3935 N BROADWAY	1 - 2 N	O78	32
SEARS STORE #2201	1801 W 21ST	1 - 2 WSW	79	32
TWIN LAKES APTS.	1945 PORTER	1 - 2 WSW	80	33
COASTAL MART #9179	527 W 13TH	1 - 2 SSW	Q81	33
WICHITA FIRE STATION #10	1655 N GROVE	1 - 2 SE	82	33
USD 259, SCHOOL SERVICE CENTER	3850 N HYDRAULIC	1 - 2 NNE	83	34
NOORI CONVENIENCE STORE	2601 N. HILLSIDE	1 - 2 E	R84	34
MART 74	2545 N. HILLSIDE	1 - 2 E	R85	35
BAKER DRYWALL & CONST.	2652 N HILLSIDE	1 - 2 E	86	35
WICHITA PARK CEMETARY SHOP	2489 N HILLSIDE	1 - 2 E	88	36
PHILLIPS 66, AMIDON	2600 AMIDON	1 - 2 W	89	36
CITGO SERVICE STATION	2700 N AMIDON	1 - 2 W	90	36
COASTAL MART #9157	1925 W 21ST	1 - 2 WSW	S91	37
GENE'S 66	801 W 13TH	1 - 2 SSW	92	37
FINA #9500	2265 N AMIDON	1 - 2 WSW	S93	37
SOUTHWESTERN BELL TELEPHONE CO	3917 N ARKANSAS	1 - 2 NNW	94	38
DANNY'S BURGERS, FORMER	2147 N HILLSIDE	1 - 2 ESE	97	39
BANTZ-HAWKINS	2015 W 21ST ST	1 - 2 WSW	99	39
Not reported	2400 E 37TH ST N	1 - 2 NE	100	40
QUALITY DISTRIBUTORS INC	3619 N POPLAR	1 - 2 NE	101	40
PLEASANT VALLEY ELEMENTARY	2000 W 29TH ST N	1 - 2 WNW	102	40
QUIRING MORUARY	3425 E 21ST	1 - 2 ESE	106	42
MCLEAN ELEMENTARY SCHOOL	2277 MARIGOLD	>2 W	108	42
BUCKNER ELEMENTARY SCHOOL	3530 E 27TH NORTH	>2 E	110	43
QWIKSTOP	2143 W 21ST	>2 WSW	111	43
USD 259, PLEASANT VALLEY MIDL	2220 W 29TH N	>2 WNW	113	44
TOTAL #1850, WICHITA	1680 N HILLSIDE	>2 ESE	114	44
WSU	1845 FAIRMOUNT	>2 ESE	115	45
PLEASANT VALLEY SERVICE INC.	2410 W 25TH ST. NORTH	>2 W	116	47
USD 259, BROOKS MIDDLE	3802 E 27TH ST N	>2 E	117	47
U-STORE-IT	3401 N HILLSDALE	>2 NE	118	47
TOWN & COUNTRY #28	1826 W 13TH	>2 SW	121	48
KORNER STORE	3800 N HILLSIDE	>2 NE	126	50
NAIL AUTO SERVICE INC	1402 N HILLSIDE	>2 SE	127	50
Not reported	4141 N SENECA	>2 NNW	136	53
USD 259, MICHENER ELEM.	2235 W 37TH	>2 NW	151	58
MAPLE GROVE CEMETERY	1000 N HILLSIDE	>2 SE	AD155	61
MCBRIDE ELECTRIC, INC.	3215 E 9TH	>2 SE	AD157	61
RAY, BILL RESIDENCE	4821 N HYDRAULIC	>2 NNE	173	68
KOCH BUSINESS SOLUTIONS LP	4111 E 37TH ST N (A)	>2 ENE	177	69

EXECUTIVE SUMMARY

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
WICHITA CHILDRENS HOME	810 N HOLYOKE	>2 SE	AN183	71
MCDONALD GOLF COURSE	1026 N ROOSEVELT	>2 SE	186	72
WICHITA CLININC BLDG	3311 E MURDOCK	>2 SE	AN187	73
WHITE CHAPEL	1806 N OLIVER	>2 ESE	188	73
QUIK TRIP #342	5001 E 21ST	>2 E	AO189	74
KMART, #7117	5010 E 21ST N	>2 E	AO191	74
<u>Lower Elevation</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
WILBERT VAULT CO.	2532 N WASHINGTON	1/4 - 1/2 E	A1	5
PETERSON, RAY	2455 N BROADWAY	1/4 - 1/2 SW	6	6
OHSE MEATS	2300 N BROADWAY	1/4 - 1/2 SSW	10	8
SUTHERLAND	522 E 21ST	1/2 - 1 S	B13	9
WICHITA FROZEN FOODS	480 E 21ST ST	1/2 - 1 SSW	B14	9
DOLD FOODS INC	2929 N OHIO	1/2 - 1 NE	D16	10
F & E WHOLESALE GROCERY, INC.	2932 NORTH OHIO	1/2 - 1 NE	D17	10
KTS	350 E 21ST STREET	1/2 - 1 SSW	E19	11
HAYES FOREST PRODUCTS	320 E 21ST	1/2 - 1 SSW	E20	11
NOVICK IRON & METAL INC.	1007 E 21ST ST	1/2 - 1 SSE	21	11
DIAMOND SHAMROCK #4185	223 E. 21ST STREET	1/2 - 1 SSW	22	12
SECURITY OIL CO.	2010 N MOSLEY	1/2 - 1 SSE	29	14
QUIKTRIP #368	363 W 21ST N	1/2 - 1 SW	30	14
INDUSTRIAL GASES OF WICHITA	550 E 17TH ST.	1 - 2 S	39	17
MCCOLLOM MOTOR CO	1730 N BROADWAY	1 - 2 SSW	K43	19
VICTOR PHILLIPS CONSTRUCTION	3250 N HYDRAULIC	1 - 2 ENE	J44	19
KANSAS DUNEBUGGY & VW SPEC.	808 E 16TH	1 - 2 S	45	19
COPELAND INTERNATIONAL TRUCKIN	1700 N BROADWAY	1 - 2 SSW	K47	20
SW BELL TELEPHONE MOBILE SYSTE	780 E 15TH ST N	1 - 2 S	55	23
KANCO DISTRIBUTING	1527 N BROADWAY	1 - 2 S	57	23
CARGILL, INC./OILSEEDS	1501 N MOSLEY	1 - 2 S	58	24
DODSON MFG CO, WICHITA	1463 BARWISE	1 - 2 S	60	24
MOO TO YOU INC	1401 N MOSLEY	1 - 2 S	67	27
SQUIRES SERVICE	302 W 13TH STREET	1 - 2 SSW	P74	30
QUIK TRIP #357	1406 N WACO	1 - 2 SSW	P76	31
NORTH HIGH SCHOOL	1437 ROCHESTER	1 - 2 SSW	Q77	31
TAILORED JEWELLERY	715 W 13TH ST	1 - 2 SSW	87	35
AMOCO OIL #7207	2201 AMIDON	1 - 2 WSW	S95	38
USD 259, MASHALL MIDDLE SCHOOL	1510 PAYNE	1 - 2 SW	96	38
7-ELEVEN #251	1161 N BROADWAY	1 - 2 S	98	39
CENTRAL STEEL INC	240 W 10TH ST	1 - 2 SSW	103	41
HOUSE OIL COMPANY	1055 N MOSLEY	1 - 2 S	104	41
LOFGREN BURKE PROPERTY	2403 E 13TH STREET	1 - 2 SE	T105	41
G&L GARAGE	2502 E 13TH	>2 SE	T107	42
ST FRANCIS REG MEDICAL CENTER	624 E 9TH	>2 S	U109	43
ST FRANCIS REGIONAL MED CENTER	929 N ST FRANCIS	>2 S	U112	44
WICHITA PUBLIC SCALES	811 N MOSLEY	>2 S	V119	48
CITY-COUNTY HEALTH DEPT.	1900 E 9TH	>2 SSE	120	48
OK TRANSFER	811 E MURDOCK	>2 S	122	49
MERCURY ELECTRIC INC	1004 E MURDOCK	>2 S	V123	49
TOWN & COUNTRY #16	803 N BROADWAY	>2 S	124	49
ST FRANCIS REGIONAL MED CTR	817 N ST FRANCIS	>2 S	125	50
AT&T, WICHITA	1516 E MURDOCK	>2 SSE	128	51
HAHNER, FOREMAN & HARNESS	724 N WABASH	>2 S	129	51
BUCKLEY INDUSTRIES INC	1600 E MURDOCK	>2 SSE	130	51
WICHITA, KING B CLUB	2323 E 9TH	>2 SSE	W131	52
WICHITA FIRE STATION # 1	731 N MAIN	>2 S	X132	52

EXECUTIVE SUMMARY

<u>Lower Elevation</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
AMERICAN RED CROSS BLOOD SERVI	707 N MAIN	>2	S X133	52
JERRY MCCRAY	1001 N. GROVE	>2	SSE W134	53
CHRISTOPHER STELL INC.	1220 BLAINE	>2	S 135	53
BYRD-SNODGRASS FUNERAL HOME	633 N BROADWAY	>2	S 137	54
CONTINENTAL BAKING	601 NE EMPORIA	>2	S 138	54
USD 259, EMERSON	2330 W 15TH	>2	WSW 139	54
SEDGWICK CO REFUELING	617 N MAIN	>2	S 140	55
INDIAN HILLS 66 SERVICE	2501 W 13TH	>2	SW Y141	55
LUCENT TECHNOLOGIES	622 E CENTRAL	>2	S Z142	55
SHIVELY TIRE INC	601 E CENTRAL	>2	S Z143	56
DOLESE-CENTRAL PLANT	826 E CENTRAL	>2	S AA144	56
JOY, KEITH (ABANDONED FACILITY	920 E CENTRAL	>2	S AA145	56
SHIVELY TIRE STORE	925 E CENTRAL	>2	S AA146	57
SEDGWICK CO, COURTHOUSE	525 N MAIN	>2	S AB147	57
SPURRIER (SUPERIOR?) CHEMICAL	515 N OHIO	>2	S AC148	57
SEDGWICK CO. HISTORIC COURTHOU	510 N. MAIN	>2	S AB149	58
ADVANCE PRODUCTS	1199 E CENTRAL	>2	S AC150	58
TOTAL #4193	2642 W. 13TH	>2	SW Y152	59
PEMCO, FORMER	455 N BROADWAY	>2	S 153	59
WICHITA WATER DEPT, CHENEY DAM	455 N MAIN, 8TH FLOOR	>2	S 154	60
WICHITA FIRE STATION #7	2828 W. 13TH ST.	>2	WSW AE156	61
YMCA, WICHITA	402 N MARKET	>2	S AF158	62
US FEDERAL COURT HOUSE	401 N MARKET	>2	S AF159	62
AMOCO #5363, WICHITA	2849 W 13TH ST	>2	WSW AE160	63
KG&E, WICHITA SERVICE BLDG	1900 E CENTRAL	>2	SSE AG161	63
COASTAL MART #9177	2012 E CENTRAL	>2	SSE AG162	64
SYD WERBIN	355 N WASHINGTON	>2	S AH163	64
FLASHER CO.	333 N ROCK ISLAND	>2	S AI164	64
ARMORED SERVICES, INC.	342 N WASHINGTON	>2	S AH165	65
WICHITA, CITY OF, WATER	1701 SIMS PARK	>2	SSW AJ166	65
ROSS SERVICE CENTER	825 EAST SECOND STREET	>2	S AI167	66
WICHITA ART MUSEUM	619 N STACKMAN	>2	SSW AJ168	66
AUTOHOUSE STUTTGART, INC.	1106 E. 2ND ST.	>2	S 169	66
THE LAW COMPANY INC	345 RIVERVIEW	>2	SSW AK170	67
FOAMY CAR WASH	13TH / ST PAUL	>2	WSW 171	67
EUROPEAN CAR COMPANY	1510 E. 2ND	>2	SSE 172	67
SHIRKMER APTS.	256 N TOPEKA	>2	S 174	68
GREENWAY MANOR	315 RIVERVIEW	>2	SSW AK175	68
ROSS SERVICE CENTER	248 N ROCK ISLAND	>2	S AL176	69
KENNEDY TIRE INC	3250 W 13TH	>2	WSW 178	69
CAR CARE	1630 E SECOND STREET	>2	SSE 179	70
FINA STATION	233 N MOSLEY	>2	S AL180	70
MISCO INDUSTRIES, INC	223 N BROADWAY	>2	S AM181	71
MISCO INDUSTRIES	223 N BROADWAY	>2	S AM182	71
Not reported	MEAD	>2	S AL184	72
SOUTHWEST PAPER	923 E 1ST (/ WASHINGT	>2	S 185	72
UNITED ROOFING & BUILDING SUPP	1321 E FIRST STREET	>2	S 190	74
MCKAY OIL CO.	369 MCLEAN BLVD NW	>2	SSW 192	75
SOUTHWEST PAPER, FORMER	150 N MOSLEY	>2	S 193	75

EXECUTIVE SUMMARY

STATE OR LOCAL ASTM SUPPLEMENTAL

AOCONCERN:Kansas AOC Areas Of Concern.

A review of the AOCONCERN list, as provided by EDR, has revealed that there is 1 AOCONCERN site within approximately 1 mile of the target property.


<u>Lower Elevation</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
NORTH INDUSTRIAL CORRIDOR		1/4 - 1/2SE	9	7

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped:

<u>Site Name</u>	<u>Database(s)</u>
H-30 DRILLING, INC.	LUST
QUIK TRIP #325	LUST
WALLY'S AUTO	LUST
FORMER SERVICE STATION (PIZZA H)	LUST


OVERVIEW MAP - 01103327.1r - Camp, Dresser & McKee, Inc.



- ★ Target Property
- ▲ Sites at elevations higher than or equal to the target property
- ◆ Sites at elevations lower than the target property
- ▲ Coal Gasification Sites
- ▨ National Priority List Sites
- ▩ Landfill Sites
- Oil & Gas pipelines
- ▨ 100-year flood zone
- ▩ 500-year flood zone
- ▧ Areas of Concern


TARGET PROPERTY: ADDRESS: CITY/STATE/ZIP: LAT/LONG:	North Industrial Corridor North Industrial Corridor Wichita KS 67219 37.7302 / 97.3310	CUSTOMER: CONTACT: INQUIRY #: DATE:	Camp, Dresser & McKee, Inc. Suzie Mead 01103327.1r December 22, 2003 5:11 pm
--	---	--	---

DETAIL MAP - 01103327.1r - Camp, Dresser & McKee, Inc.



- ★ Target Property
- ▲ Sites at elevations higher than or equal to the target property
- ◆ Sites at elevations lower than the target property
- ▲ Coal Gasification Sites
- Sensitive Receptors
- National Priority List Sites
- Landfill Sites

- Oil & Gas pipelines
- 100-year flood zone
- 500-year flood zone
- Areas of Concern



TARGET PROPERTY:	North Industrial Corridor	CUSTOMER:	Camp, Dresser & McKee, Inc.
ADDRESS:	North Industrial Corridor	CONTACT:	Suzie Mead
CITY/STATE/ZIP:	Wichita KS 67219	INQUIRY #:	01103327.1r
LAT/LONG:	37.7302 / 97.3310	DATE:	December 22, 2003 5:12 pm

MAP FINDINGS SUMMARY

<u>Database</u>	<u>Target Property</u>	<u>Search Distance (Miles)</u>	<u>< 1/8</u>	<u>1/8 - 1/4</u>	<u>1/4 - 1/2</u>	<u>1/2 - 1</u>	<u>> 1</u>	<u>Total Plotted</u>
<u>STATE ASTM STANDARD</u>								
LUST		3.000	0	0	9	27	156	192
<u>FEDERAL ASTM SUPPLEMENTAL</u>								
US BROWNFIELDS		0.500	0	0	0	NR	NR	0
<u>STATE OR LOCAL ASTM SUPPLEMENTAL</u>								
AOCONCERN		1.000	0	0	1	0	NR	1
<u>BROWNFIELDS DATABASES</u>								
US BROWNFIELDS		0.500	0	0	0	NR	NR	0

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

A1	WILBERT VAULT CO.		LUST	S105434760
East	2532 N WASHINGTON			N/A
1/4-1/2	WICHITA, KS 67219			
1368 ft.				

Site 1 of 2 in cluster A

**Relative:
Lower**

LUST:

Facility ID: 88888
 Project Name: WILBERT VAULT
 Project Number: U208700165
 Project Num Extension: Not reported
 Quarter Fraction of Section: NWNWSE
 Section, Township, Range: 2701E04
 Buried Tank Leak Assessment Date: 04/14/1989
 Initial Report Date: 04/14/1989

**Actual:
1309 ft.**

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

2	COPELAND TRUCKING, WICHITA		LUST	S102406758
West	2655 N BROADWAY			N/A
1/4-1/2	WICHITA, KS 67219			
1431 ft.				

**Relative:
Higher**

LUST:

Facility ID: 29168
 Project Name: COPELAND TRUCKING
 Project Number: U208700639
 Project Num Extension: Not reported
 Quarter Fraction of Section: SESENE
 Section, Township, Range: 2701E05
 Buried Tank Leak Assessment Date: 03/20/1991
 Initial Report Date: 07/10/1990

**Actual:
1317 ft.**

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 29168
 Project Name: COPELAND TRUCKING
 Project Number: U208700639
 Project Num Extension: B
 Quarter Fraction of Section: SENE
 Section, Township, Range: 2701E05
 Buried Tank Leak Assessment Date: 01/28/1991
 Initial Report Date: 01/22/1991
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

A3	WICHITA SERVICE CENTER		LUST	U000873841
ENE	1021 EAST 26TH STREET NORTH			N/A
1/4-1/2	WICHITA, KS 67219			
1437 ft.				

Site 2 of 2 in cluster A

**Relative:
Higher**

LUST:

Facility ID: 27938
 Project Name: WESTERN RESOURCES - KPL
 Project Number: U208701244
 Project Num Extension: Not reported
 Quarter Fraction of Section: SWSWSWNE
 Section, Township, Range: 2701E04
 Buried Tank Leak Assessment Date: 10/29/1993

**Actual:
1311 ft.**

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WICHITA SERVICE CENTER (Continued)

U000873841

Initial Report Date: 10/13/1993
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

4
NNW
1/4-1/2
1658 ft.

KANSAS METALS CO.
2829 N EMPORIA
WICHITA, KS 67219

LUST S102406695
N/A

Relative:
Equal

LUST:

Facility ID: 25571
Project Name: KANSAS METALS CO
Project Number: U208700329
Project Num Extension: Not reported
Quarter Fraction of Section: SENWNW
Section, Township, Range: 2701E04
Buried Tank Leak Assessment Date: 01/18/1990
Initial Report Date: 01/18/1990
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

Actual:
1310 ft.

5
West
1/4-1/2
1747 ft.

SPECIALIZED TRANSPORT SERVICE
2614 N MARKET
WICHITA, KS 67219

LUST S101833873
N/A

Relative:
Higher

LUST:

Facility ID: 26147
Project Name: SPECIALIZED TRANSPORT SERVICE
Project Number: U208701311
Project Num Extension: Not reported
Quarter Fraction of Section: SESESENE
Section, Township, Range: 2701E05
Buried Tank Leak Assessment Date: 03/29/1994
Initial Report Date: 03/22/1994
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Actual:
1315 ft.

6
SW
1/4-1/2
1775 ft.

PETERSON, RAY
2455 N BROADWAY
WICHITA, KS

LUST S103370614
N/A

Relative:
Lower

LUST:

Facility ID: 81632
Project Name: PETERSON, RAY
Project Number: U208712108
Project Num Extension: Not reported
Quarter Fraction of Section: NESENESE
Section, Township, Range: 2701E05
Buried Tank Leak Assessment Date: 09/21/1998
Initial Report Date: 09/21/1998
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Actual:
1306 ft.

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

Site

Database(s)

EDR ID Number
 EPA ID Number

PETERSON, RAY (Continued)

S103370614

7
NNE
1/4-1/2
1973 ft.

EXCELL CORPORATION
2901 N MEAD
WICHITA, KS 67219

LUST S101713800
N/A

Relative:
Higher

Actual:
1316 ft.

LUST:

Facility ID: 04965
 Project Name: EXCELL CORP
 Project Number: U208700284
 Project Num Extension: Not reported
 Quarter Fraction of Section: NENW
 Section, Township, Range: 2701E04
 Buried Tank Leak Assessment Date: 07/05/1990
 Initial Report Date: 11/21/1989

Facility Status: **HOLD** - A 'Hold' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state but because of circumstances at the site, the state does not require that additional remedial work be performed at this time. As the circumstances may change, the state may then re-assign the site a different status.

8
ENE
1/4-1/2
2175 ft.

BROWNING FERRIS INDUSTRIES
2745 NORTH OHIO STREET
WICHITA, KS 67219

LUST 1000438083
KSD980860639

Relative:
Higher

Actual:
1317 ft.

LUST:

Facility ID: 04519
 Project Name: BFI
 Project Number: U208700938
 Project Num Extension: Not reported
 Quarter Fraction of Section: NWSWNW
 Section, Township, Range: 2701E04
 Buried Tank Leak Assessment Date: 05/11/1992
 Initial Report Date: 05/07/1992

Facility Status: **MONITOR** - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

9
SE
1/4-1/2
2236 ft.

NORTH INDUSTRIAL CORRIDOR
WICHITA, KS

AOCONCERN CKS0000002
N/A

Relative:
Lower

Actual:
1302 ft.

AOCONCERN:

KS Areas of concern.

MAP FINDINGS

Map ID							
Direction							
Distance							
Distance (ft.)							
Elevation	Site				Database(s)	EPA ID Number	EDR ID Number

B13	SUTHERLAND		LUST	S102406718
South	522 E 21ST			N/A
1/2-1	WICHITA, KS 67214			
2813 ft.				

Site 1 of 2 in cluster B

Relative:
Lower

LUST:

Facility ID:	80033			
Project Name:	SUTHERLAND LUMBER CO			
Project Number:	U208700434			
Project Num Extension:	Not reported			
Quarter Fraction of Section:	SESW			
Section, Township, Range:	2701E04			
Buried Tank Leak Assessment Date:	04/04/1990			
Initial Report Date:	04/04/1990			
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.			

B14	WICHITA FROZEN FOODS		LUST	U000197560
SSW	480 E 21ST ST			N/A
1/2-1	WICHITA, KS 67214			
2847 ft.				

Site 2 of 2 in cluster B

Relative:
Lower

LUST:

Facility ID:	22816			
Project Name:	WICHITA FROZEN FOODS			
Project Number:	U208710393			
Project Num Extension:	Not reported			
Quarter Fraction of Section:	SESWSWSW			
Section, Township, Range:	2701E04			
Buried Tank Leak Assessment Date:	05/30/1995			
Initial Report Date:	05/23/1995			
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.			

C15	KAMEN (OLD EXCELL PLANT)		LUST	S101833409
SSE	900 E 21ST			N/A
1/2-1	WICHITA, KS 67214			
2910 ft.				

Site 1 of 2 in cluster C

Relative:
Higher

LUST:

Facility ID:	80065			
Project Name:	KAMEN (EXCELL PLANT)			
Project Number:	U208700463			
Project Num Extension:	Not reported			
Quarter Fraction of Section:	NENW			
Section, Township, Range:	2701E04			
Buried Tank Leak Assessment Date:	07/03/1990			
Initial Report Date:	03/20/1990			
Facility Status:	HOLD - A 'Hold' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state but because of circumstances at the site, the state does not require that additional remedial work be performed at this time. As the circumstances may change, the state may then re-assign the site a different status.			

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

D16 NE 1/2-1 2937 ft.	DOLD FOODS INC 2929 N OHIO WICHITA, KS 67219	LUST	1000183162 KSD984970988
--	---	-------------	--

Site 1 of 2 in cluster D

Relative:
Lower

LUST:

Facility ID:	13671		
Project Name:	DOLD FOODS		
Project Number:	U208700677		
Project Num Extension:	Not reported		
Quarter Fraction of Section:	NWNWNE		
Section, Township, Range:	2701E04		
Buried Tank Leak Assessment Date:	03/21/1991		
Initial Report Date:	03/19/1991		
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.		

D17 NE 1/2-1 2959 ft.	F & E WHOLESALE GROCERY, INC. 2932 NORTH OHIO WICHITA, KS 67219	LUST	U000873890 N/A
--	--	-------------	---------------------------------

Site 2 of 2 in cluster D

Relative:
Lower

LUST:

Facility ID:	28078		
Project Name:	F & E WHOLESALE		
Project Number:	U208700604		
Project Num Extension:	Not reported		
Quarter Fraction of Section:	NWNE		
Section, Township, Range:	2701E04		
Buried Tank Leak Assessment Date:	11/16/1990		
Initial Report Date:	11/16/1990		
Facility Status:	ACTIVE - An 'Active' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state. Active sites require that additional remedial work be completed to bring the site into compliance with state and federal law.		

C18 SSE 1/2-1 2994 ft.	NATIONAL BY-PRODUCTS 2155 N MOSLEY WICHITA, KS 67214	LUST	S103236716 N/A
---	---	-------------	---------------------------------

Site 2 of 2 in cluster C

Relative:
Higher

LUST:

Facility ID:	04540		
Project Name:	NATIONAL BY-PRODUCTS, WICHITA		
Project Number:	U208700827		
Project Num Extension:	Not reported		
Quarter Fraction of Section:	NENENW		
Section, Township, Range:	2701E09		
Buried Tank Leak Assessment Date:	10/24/1991		
Initial Report Date:	10/24/1991		
Facility Status:	MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.		

Facility ID:	04540		
Project Name:	NATIONAL BY-PRODUCTS, WICHITA		
Project Number:	U208711190		
Project Num Extension:	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

NATIONAL BY-PRODUCTS (Continued)

S103236716

Quarter Fraction of Section: NENENW
Section, Township, Range: 2701E09
Buried Tank Leak Assessment Date: 12/04/1991
Initial Report Date: 12/04/1991
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

E19 KTS LUST S103370334
SSW 350 E 21ST STREET N/A
1/2-1 WICHITA, KS 67214
3001 ft.

Site 1 of 2 in cluster E

**Relative:
Lower**

LUST:

**Actual:
1300 ft.**

Facility ID: 80046
Project Name: KTS
Project Number: U208700234
Project Num Extension: Not reported
Quarter Fraction of Section: SWSWSW
Section, Township, Range: 2701E04
Buried Tank Leak Assessment Date: 01/30/1990
Initial Report Date: 08/30/1989
Facility Status: HOLD - A 'Hold' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state but because of circumstances at the site, the state does not require that additional remedial work be performed at this time. As the circumstances may change, the state may then re-assign the site a different status.

E20 HAYES FOREST PRODUCTS LUST S101833280
SSW 320 E 21ST N/A
1/2-1 WICHITA, KS 67214
3043 ft.

Site 2 of 2 in cluster E

**Relative:
Lower**

LUST:

**Actual:
1302 ft.**

Facility ID: 80081
Project Name: HAYES FOREST PRODUCTS
Project Number: U208700217
Project Num Extension: Not reported
Quarter Fraction of Section: SWSWSW
Section, Township, Range: 2701E04
Buried Tank Leak Assessment Date: 08/31/1989
Initial Report Date: 08/30/1989
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

21 NOVICK IRON & METAL INC. LUST S102282594
SSE 1007 E 21ST ST N/A
1/2-1 WICHITA, KS 67214
3098 ft.

**Relative:
Lower**

LUST:

**Actual:
1306 ft.**

Facility ID: 28779
Project Name: NOVICK IRON & METAL
Project Number: U208700275
Project Num Extension: Not reported
Quarter Fraction of Section: NWNE
Section, Township, Range: 2701E09

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

NOVICK IRON & METAL INC. (Continued)

S102282594

Buried Tank Leak Assessment Date: 04/27/1990
Initial Report Date: 12/13/1989
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

22
SSW
1/2-1
3203 ft.

DIAMOND SHAMROCK #4185
223 E. 21ST STREET
WICHITA, KS 67214

LUST **U000716049**
N/A

Relative:
Lower

LUST:

Actual:
1306 ft.

Facility ID: 06988
Project Name: TPI PETROLEUM #4185
Project Number: U208712898
Project Num Extension: Not reported
Quarter Fraction of Section: NENENENE
Section, Township, Range: 2701E08
Buried Tank Leak Assessment Date: 04/06/2000
Initial Report Date: 11/08/1999
Facility Status: ACTIVE - An 'Active' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state. Active sites require that additional remedial work be completed to bring the site into compliance with state and federal law.

F23
NE
1/2-1
3310 ft.

UNIVERSAL QUICKMART #11
2950 N OHIO
WICHITA, KS 67219

LUST **S104938309**
N/A

Relative:
Higher

Site 1 of 2 in cluster F

LUST:

Actual:
1312 ft.

Facility ID: 26513
Project Name: UNIVERSAL QUICK MART #11
Project Number: U208700541
Project Num Extension: Not reported
Quarter Fraction of Section: NENWNE
Section, Township, Range: 2701E04
Buried Tank Leak Assessment Date: 03/31/1989
Initial Report Date: 03/31/1989
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

F24
NE
1/2-1
3422 ft.

GARDEN WISE
1515 E 29 N
WICHITA, KS 67219

LUST **S103370328**
N/A

Relative:
Higher

Site 2 of 2 in cluster F

LUST:

Actual:
1313 ft.

Facility ID: 19451
Project Name: GARDEN WISE
Project Number: U208700138
Project Num Extension: Not reported
Quarter Fraction of Section: NENWNE
Section, Township, Range: 2701E04
Buried Tank Leak Assessment Date: 04/04/1989
Initial Report Date: 04/04/1989

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

Database(s) EDR ID Number
EPA ID Number

GARDEN WISE (Continued)

S103370328

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

**25
NW
1/2-1
3447 ft.**

**RAY'S ELECTRIC INC.
2934 FAIRVIEW
WICHITA, KS 67204**

**LUST S101833533
N/A**

**Relative:
Higher**

LUST:

Facility ID: 26991
Project Name: RAY'S ELECTRIC
Project Number: U208700711
Project Num Extension: Not reported
Quarter Fraction of Section: NWNENE
Section, Township, Range: 2701E05
Buried Tank Leak Assessment Date: 06/13/1991
Initial Report Date: 06/13/1991

**Actual:
1311 ft.**

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

**26
WSW
1/2-1
3805 ft.**

**HOLDERS REAL ESTATE,(ABANDONDED)
620 W 24TH
WICHITA, KS 67204**

**LUST S101833597
N/A**

**Relative:
Equal**

LUST:

Facility ID: 80089
Project Name: HOLDERS REAL ESTATE
Project Number: U208700813
Project Num Extension: Not reported
Quarter Fraction of Section: NWNWSE
Section, Township, Range: 2701E05
Buried Tank Leak Assessment Date: 11/22/1991
Initial Report Date: 11/22/1991

**Actual:
1310 ft.**

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

**27
East
1/2-1
3893 ft.**

**2645 NEW YORK AVE.
WICHITA, KS**

**LUST S102406683
N/A**

**Relative:
Higher**

LUST:

Facility ID: 29769
Project Name: WICHITA FUELING FACILITY
Project Number: U208700240
Project Num Extension: Not reported
Quarter Fraction of Section: Not reported
Section, Township, Range: 2701E04
Buried Tank Leak Assessment Date: 09/01/1989
Initial Report Date: 08/31/1989

**Actual:
1313 ft.**

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 29769
Project Name: WICHITA FUELING FAC, CAR REPAIR
Project Number: U208711017
Project Num Extension: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

(Continued)

S102406683

Quarter Fraction of Section: SENESENE
 Section, Township, Range: 2701E04
 Buried Tank Leak Assessment Date: 03/03/1993
 Initial Report Date: 01/29/1993
 Facility Status: ACTIVE - An 'Active' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state. Active sites require that additional remedial work be completed to bring the site into compliance with state and federal law.

28 TOWN & COUNTRY #19 (TOTAL 1847) LUST S104938329
 West 2600 N ARKANSAS N/A
 1/2-1 WICHITA, KS 67204
 3960 ft.

Relative: Higher LUST:
 Facility ID: 06958
 Project Name: TOWN & COUNTRY #19 (TOTAL 1847)
 Actual: 1314 ft. Project Number: U208701167
 Project Num Extension: Not reported
 Quarter Fraction of Section: SWSWSWNE
 Section, Township, Range: 2701E05
 Buried Tank Leak Assessment Date: 05/12/1993
 Initial Report Date: 05/04/1993
 Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

29 SECURITY OIL CO. LUST S102406714
 SSE 2010 N MOSLEY N/A
 1/2-1 WICHITA, KS 67214
 4101 ft.

Relative: Lower LUST:
 Facility ID: 26003
 Project Name: SECURITY OIL
 Actual: 1306 ft. Project Number: U208700421
 Project Num Extension: Not reported
 Quarter Fraction of Section: NW
 Section, Township, Range: 2701E09
 Buried Tank Leak Assessment Date: 11/16/1989
 Initial Report Date: 11/16/1990
 Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

30 QUIKTRIP #368 LUST U003083632
 SW 363 W 21ST N N/A
 1/2-1 WICHITA, KS 67203
 4112 ft.

Relative: Lower LUST:
 Facility ID: 07293
 Project Name: QUIK TRIP #368
 Actual: 1307 ft. Project Number: U208711089
 Project Num Extension: Not reported
 Quarter Fraction of Section: NWNENWNE
 Section, Township, Range: 2701E08
 Buried Tank Leak Assessment Date: 07/26/1996
 Initial Report Date: 07/22/1996

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

QUIKTRIP #368 (Continued)

U003083632

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

**G31
NNW
1/2-1
4235 ft.**

**ROOF MECHANICS INC
3205 N BROADWAY
WICHITA, KS 67219**

**LUST 1000227054
N/A**

Site 1 of 2 in cluster G

**Relative:
Higher**

**Actual:
1316 ft.**

LUST:

Facility ID: 23973
Project Name: ROOF MECHANICS
Project Number: U208700283
Project Num Extension: Not reported
Quarter Fraction of Section: SENESE
Section, Township, Range: 2601E32
Buried Tank Leak Assessment Date: 01/19/1990
Initial Report Date: 12/12/1989

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

**G32
NNW
1/2-1
4591 ft.**

**WICHITA FIRE STATION #3
3261 N BROADWAY
WICHITA, KS 67219**

**LUST S101833693
N/A**

Site 2 of 2 in cluster G

**Relative:
Higher**

**Actual:
1317 ft.**

LUST:

Facility ID: 09162
Project Name: FIRE STATION #3, WICHITA
Project Number: U208700987
Project Num Extension: Not reported
Quarter Fraction of Section: NESENESE
Section, Township, Range: 2601E32
Buried Tank Leak Assessment Date: 07/23/1992
Initial Report Date: 07/22/1992

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

**33
SW
1/2-1
4735 ft.**

**SHOP-A-LOT
621 W 21ST
WICHITA, KS 67203**

**LUST S102406662
N/A**

**Relative:
Higher**

**Actual:
1313 ft.**

LUST:

Facility ID: 28756
Project Name: SHOP-A-LOT
Project Number: U208700179
Project Num Extension: Not reported
Quarter Fraction of Section: NWNWNWNE
Section, Township, Range: 2701E08
Buried Tank Leak Assessment Date: 06/22/1989
Initial Report Date: 02/09/1989

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

SHOP-A-LOT (Continued)

Database(s) EDR ID Number
EPA ID Number

S102406662

34
South
1/2-1
4772 ft.

NATIONAL BY-PRODUCTS
518 E 18TH ST.
WICHITA, KS 67214

LUST S105434761
N/A

Relative:
Higher

LUST:

Facility ID: 88888
Project Name: NATIONAL BY-PRODUCTS, WICHITA
Project Number: U208700206
Project Num Extension: Not reported
Quarter Fraction of Section: SWNW
Section, Township, Range: 2701E09
Buried Tank Leak Assessment Date: 07/27/1989
Initial Report Date: 07/19/1989
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

35
South
1/2-1
4839 ft.

PURINA MILLS INC
414 E 18TH
WICHITA, KS 67214

LUST 1001219338
KSR000009605

Relative:
Higher

LUST:

Facility ID: 26340
Project Name: PURINA MILLS
Project Number: U208700103
Project Num Extension: A
Quarter Fraction of Section: SWNW
Section, Township, Range: 2701E09
Buried Tank Leak Assessment Date: 05/17/1988
Initial Report Date: 05/17/1988
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 26340
Project Name: PURINA MILLS
Project Number: U208700103
Project Num Extension: B
Quarter Fraction of Section: NW
Section, Township, Range: 2701E09
Buried Tank Leak Assessment Date: 05/09/1991
Initial Report Date: 05/09/1991
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

H36
SSW
1/2-1
4937 ft.

BOBS TRANSMISSION INC
1900 N BROADWAY
WICHITA, KS

LUST S105051533
N/A

Site 1 of 2 in cluster H

Relative:
Equal

LUST:

Actual:
1310 ft.

Facility ID: 81806
Project Name: BOB'S TRANSMISSIONS INC
Project Number: U208713100
Project Num Extension: Not reported
Quarter Fraction of Section: NWSWNW

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

BOBS TRANSMISSION INC (Continued)

S105051533

Section, Township, Range: 2701E09
Buried Tank Leak Assessment Date: 05/11/2001
Initial Report Date: 05/11/2001
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

**H37
SSW
1/2-1
5043 ft.**

**WICHITA, CITY OF
1901 N MARKET
WICHITA, KS 67214**

**LUST S101833294
N/A**

Site 2 of 2 in cluster H

**Relative:
Higher**

LUST:

**Actual:
1312 ft.**

Facility ID: 80110
Project Name: WICHITA, CITY OF, EMERGENCY
Project Number: U208700238
Project Num Extension: Not reported
Quarter Fraction of Section: Not reported
Section, Township, Range: Not reported
Buried Tank Leak Assessment Date: 09/15/1989
Initial Report Date: 09/08/1989
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

**38
South
> 1
5357 ft.**

**ALLEN'S CONCRETE
1820 N MOSLEY
WICHITA, KS 67204**

**LUST S101833595
N/A**

**Relative:
Higher**

LUST:

**Actual:
1311 ft.**

Facility ID: 23875
Project Name: ALLENS CONCRETE,
Project Number: U208700811
Project Num Extension: Not reported
Quarter Fraction of Section: NWSESE
Section, Township, Range: 2701E09
Buried Tank Leak Assessment Date: 12/27/1991
Initial Report Date: Not reported
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

**39
South
> 1
5423 ft.**

**INDUSTRIAL GASES OF WICHITA
550 E 17TH ST.
WICHITA, KS 67214**

**LUST S102406725
N/A**

**Relative:
Lower**

LUST:

**Actual:
1306 ft.**

Facility ID: 80083
Project Name: INDUSTRIAL GASES
Project Number: U208700449
Project Num Extension: Not reported
Quarter Fraction of Section: SENE
Section, Township, Range: 2701E08
Buried Tank Leak Assessment Date: 06/25/1990
Initial Report Date: 06/04/1990
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

INDUSTRIAL GASES OF WICHITA (Continued)

S102406725

<p>40 WNW > 1 5549 ft.</p>	<p>MCBRIDE DEHMER CONSTRUCTION 2855 WOODLAND WICHITA, KS</p>	<p>LUST</p>	<p>S101833747 N/A</p>
---	---	--------------------	---

<p>Relative: Higher</p>	<p>Actual: 1316 ft.</p>	<p>LUST: Facility ID: 80054 Project Name: MCBRIDE DEHMER CONSTRUCTION Project Number: U208701079 Project Num Extension: Not reported Quarter Fraction of Section: NESENWNW Section, Township, Range: 2701E05 Buried Tank Leak Assessment Date: 04/04/1989 Initial Report Date: 04/04/1989 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.</p>
---	---	--

<p>I41 ESE > 1 5794 ft.</p>	<p>AMOCO #2148 2001 E. 21ST ST. WICHITA, KS 67214</p>	<p>LUST</p>	<p>S103370351 N/A</p>
--	--	--------------------	---

<p>Relative: Higher</p>	<p>Actual: 1316 ft.</p>	<p>Site 1 of 2 in cluster I LUST: Facility ID: 25211 Project Name: AMOCO #2148, WICHITA Project Number: U208701197 Project Num Extension: Not reported Quarter Fraction of Section: NENW Section, Township, Range: 2701E10 Buried Tank Leak Assessment Date: 08/27/1991 Initial Report Date: 08/01/1991 Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.</p>
---	---	--

<p>J42 ENE > 1 5887 ft.</p>	<p>WHITESTAR 3223 N HYDRAULIC WICHITA, KS 67219</p>	<p>LUST</p>	<p>S101833616 N/A</p>
--	--	--------------------	---

<p>Relative: Higher</p>	<p>Actual: 1322 ft.</p>	<p>Site 1 of 2 in cluster J LUST: Facility ID: 27032 Project Name: WHITESTAR Project Number: U208700851 Project Num Extension: Not reported Quarter Fraction of Section: SWNWSW Section, Township, Range: 2601E34 Buried Tank Leak Assessment Date: 01/09/1992 Initial Report Date: 01/08/1992 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.</p>
---	---	---

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EPA ID Number

WHITESTAR (Continued)

S101833616

<p>K43 SSW > 1 6026 ft.</p>	<p>MCCOLLOM MOTOR CO 1730 N BROADWAY WICHITA, KS 67214</p>	<p>LUST</p>	<p>S101833694 N/A</p>
--	---	--------------------	---

Site 1 of 2 in cluster K

Relative:
Lower

LUST:

Facility ID:	80055		
Project Name:	MCCOLLOM MOTOR		
Project Number:	U208700988		
Project Num Extension:	Not reported		
Quarter Fraction of Section:	NWNWNWSW		
Section, Township, Range:	2701E09		
Buried Tank Leak Assessment Date:	07/23/1992		
Initial Report Date:	07/23/1992		
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.		

<p>J44 ENE > 1 6037 ft.</p>	<p>VICTOR PHILLIPS CONSTRUCTION 3250 N HYDRAULIC WICHITA, KS 67219</p>	<p>LUST</p>	<p>S102406647 N/A</p>
--	---	--------------------	---

Site 2 of 2 in cluster J

Relative:
Lower

LUST:

Facility ID:	80013		
Project Name:	VICTOR PHILLIPS CONSTRUCTION		
Project Number:	U208700121		
Project Num Extension:	Not reported		
Quarter Fraction of Section:	NWNWSW		
Section, Township, Range:	2601E34		
Buried Tank Leak Assessment Date:	12/20/1988		
Initial Report Date:	12/19/1988		
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.		

<p>45 South > 1 6121 ft.</p>	<p>KANSAS DUNEBUGGY & VW SPEC. 808 E 16TH WICHITA, KS 67214</p>	<p>LUST</p>	<p>S102406766 N/A</p>
---	--	--------------------	---

Relative:
Lower

LUST:

Facility ID:	10128		
Project Name:	KANSAS DUNEBUGGY		
Project Number:	U208700707		
Project Num Extension:	Not reported		
Quarter Fraction of Section:	NESW		
Section, Township, Range:	2701E09		
Buried Tank Leak Assessment Date:	12/26/1989		
Initial Report Date:	12/21/1989		
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.		

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

I46 ESE > 1 6136 ft.	COASTAL MART #9180 2102 E 21ST WICHITA, KS 67219	LUST	S101833598 N/A
--	---	-------------	---------------------------------

Site 2 of 2 in cluster I

Relative:
Higher

Actual:
1315 ft.

LUST:

Facility ID:	07231
Project Name:	COASTAL MART #9180
Project Number:	U208700814
Project Num Extension:	Not reported
Quarter Fraction of Section:	NWNWENW
Section, Township, Range:	2701E10
Buried Tank Leak Assessment Date:	11/26/1991
Initial Report Date:	11/26/1991
Facility Status:	MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

K47 SSW > 1 6228 ft.	COPELAND INTERNATIONAL TRUCKIN 1700 N BROADWAY WICHITA, KS 67214	LUST	S101833547 N/A
--	---	-------------	---------------------------------

Site 2 of 2 in cluster K

Relative:
Lower

Actual:
1302 ft.

LUST:

Facility ID:	13030
Project Name:	COPELAND INTL TRUCKING
Project Number:	U208700734
Project Num Extension:	Not reported
Quarter Fraction of Section:	SESENE
Section, Township, Range:	2701E08
Buried Tank Leak Assessment Date:	08/01/1991
Initial Report Date:	08/01/1991
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

48 NNE > 1 6295 ft.	HOME OIL CO INC 3511 NORTH OHIO WICHITA, KS 67219	LUST	1000197834 KSD981718919
---	--	-------------	--

Relative:
Higher

Actual:
1322 ft.

LUST:

Facility ID:	28895
Project Name:	HOME OIL CO
Project Number:	U208712212
Project Num Extension:	Not reported
Quarter Fraction of Section:	SE
Section, Township, Range:	2601E33
Buried Tank Leak Assessment Date:	12/11/1998
Initial Report Date:	12/11/1998
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID	Direction	Distance	Distance (ft.)	Elevation	Site	Database(s)	EDR ID Number	EPA ID Number
L49	ESE	> 1	6361 ft.		H & M CORNER STORE 2157 E 21ST WICHITA, KS 67214	LUST	S102406876	N/A
Site 1 of 2 in cluster L								
Relative: Higher								
LUST:								
Facility ID: 81371								
Project Name: H & M CORNER STORE								
Project Number: U208710664								
Project Num Extension: Not reported								
Quarter Fraction of Section: NENWNENW								
Section, Township, Range: 2701E10								
Buried Tank Leak Assessment Date: 10/24/1995								
Initial Report Date: 10/24/1995								
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.								
<hr/>								
50	ESE	> 1	6361 ft.		INSTITUTE OF LOGOPEDICS 2400 JARDINE WICHITA, KS 67219	LUST	1000413991	N/A
Relative: Higher								
LUST:								
Facility ID: 06103								
Project Name: INSTITUTE OF LOGOPEDICS, WICHITA, 2400 N								
Project Number: U208700214								
Project Num Extension: Not reported								
Quarter Fraction of Section: Not reported								
Section, Township, Range: Not reported								
Buried Tank Leak Assessment Date: 12/11/1989								
Initial Report Date: 12/11/1989								
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.								
<hr/>								
51	WNW	> 1	6373 ft.		KMVR RADIO TRANSMITTER 2829 SALINA WICHITA, KS 67203	LUST	S104105245	N/A
Relative: Higher								
LUST:								
Facility ID: 29616								
Project Name: KMVR RADIO TRANSMITTER								
Project Number: U208712623								
Project Num Extension: Not reported								
Quarter Fraction of Section: SWNWNW								
Section, Township, Range: 2701E05								
Buried Tank Leak Assessment Date: 07/22/1999								
Initial Report Date: 07/22/1999								
Facility Status: HOLD - A 'Hold' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state but because of circumstances at the site, the state does not require that additional remedial work be performed at this time. As the circumstances may change, the state may then re-assign the site a different status.								

MAP FINDINGS

Map ID							
Direction							
Distance							
Distance (ft.)							
Elevation	Site			Database(s)		EDR ID Number	EPA ID Number

52	ARKANSAS AVE ELEMENTARY		
NW	3361 ARKANSAS	LUST	S101833867
> 1	WICHITA, KS 67204		N/A
6484 ft.			

Relative: Higher

Actual: 1316 ft.

LUST:

Facility ID: 08897

Project Name: USD 259, ARKANSAS AVE ELEMENTARY

Project Number: U208701305

Project Num Extension: Not reported

Quarter Fraction of Section: NENENESW

Section, Township, Range: 2601E32

Buried Tank Leak Assessment Date: 03/31/1994

Initial Report Date: 03/31/1994

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

L53	WILLIAMS & SONS, WICHITA		
ESE	2203 E 21ST	LUST	S101837961
> 1	WICHITA, KS 67214		N/A
6552 ft.			

Site 2 of 2 in cluster L

Relative: Higher

Actual: 1312 ft.

LUST:

Facility ID: 22918

Project Name: WILLIAMS & SONS

Project Number: U208710392

Project Num Extension: Not reported

Quarter Fraction of Section: NWNENENW

Section, Township, Range: 2701E10

Buried Tank Leak Assessment Date: 05/11/1995

Initial Report Date: 12/09/1994

Facility Status: ACTIVE - An 'Active' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state. Active sites require that additional remedial work be completed to bring the site into compliance with state and federal law.

M54	SALVATION ARMY		
North	3601 N ST FRANCIS	LUST	S102406696
> 1	WICHITA, KS		N/A
6670 ft.			

Site 1 of 2 in cluster M

Relative: Higher

Actual: 1316 ft.

LUST:

Facility ID: 80029

Project Name: SALVATION ARMY

Project Number: U208700344

Project Num Extension: Not reported

Quarter Fraction of Section: NWNW

Section, Township, Range: 2601E33

Buried Tank Leak Assessment Date: 02/19/1990

Initial Report Date: 02/16/1990

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

55	SW BELL TELEPHONE MOBILE SYSTE	LUST	S102406715
South	780 E 15TH ST N		N/A
> 1	WICHITA, KS		
6761 ft.			

Relative:	LUST:		
Lower	Facility ID:	08867	
	Project Name:	SW BELL TELEPHONE	
Actual:	Project Number:	U208700426	
1303 ft.	Project Num Extension:	Not reported	
	Quarter Fraction of Section:	Not reported	
	Section, Township, Range:	Not reported	
	Buried Tank Leak Assessment Date:	05/17/1990	
	Initial Report Date:	05/17/1990	
	Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.	

M56	JAY CARLLEY, INC.	LUST	S101833881
North	3615 N EMPORIA		N/A
> 1	WICHITA, KS 67219		
6781 ft.			

	Site 2 of 2 in cluster M		
Relative:	LUST:		
Higher	Facility ID:	00465	
	Project Name:	JAY CARLLEY, INC.	
Actual:	Project Number:	U208701336	
1320 ft.	Project Num Extension:	Not reported	
	Quarter Fraction of Section:	SWSNWNW	
	Section, Township, Range:	2601E33	
	Buried Tank Leak Assessment Date:	06/22/1994	
	Initial Report Date:	06/22/1994	
	Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.	

57	KANCO DISTRIBUTING	LUST	S102689579
South	1527 N BROADWAY		N/A
> 1	WICHITA, KS 67277		
7338 ft.			

Relative:	LUST:		
Lower	Facility ID:	81552	
	Project Name:	KANCO DISTRIBUTING	
Actual:	Project Number:	U208711633	
1305 ft.	Project Num Extension:	Not reported	
	Quarter Fraction of Section:	NENESESE	
	Section, Township, Range:	2701E08	
	Buried Tank Leak Assessment Date:	08/01/1997	
	Initial Report Date:	07/03/1997	
	Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.	

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

58 South > 1 7456 ft.	CARGILL, INC./OILSEEDS 1501 N MOSLEY WICHITA, KS 67214	LUST	1000616231 N/A
---------------------------------------	---	-------------	--------------------------

Relative: LUST:
Lower

Facility ID: 27331
 Project Name: CARGILL INC
 Project Number: U208700697
 Project Num Extension: Not reported
 Quarter Fraction of Section: SESW
 Section, Township, Range: 2701E09
 Buried Tank Leak Assessment Date: 05/09/1991
 Initial Report Date: 05/08/1991
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 27331
 Project Name: CARGILL INC
 Project Number: U208700697
 Project Num Extension: B
 Quarter Fraction of Section: SWNESW
 Section, Township, Range: 2701E09
 Buried Tank Leak Assessment Date: 08/16/1991
 Initial Report Date: 08/15/1991
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

59 WNW > 1 7611 ft.	SMALL BUSINESS ADMIN 1325 W 29TH ST N WICHITA, KS 67204	LUST	S102406755 N/A
-------------------------------------	--	-------------	--------------------------

Relative: LUST:
Higher

Facility ID: 80031
 Project Name: SMALL BUSINESS ADMIN
 Project Number: U208700613
 Project Num Extension: Not reported
 Quarter Fraction of Section: NE
 Section, Township, Range: 2701E06
 Buried Tank Leak Assessment Date: 12/10/1990
 Initial Report Date: 12/10/1990
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

60 South > 1 7661 ft.	DODSON MFG CO, WICHITA 1463 BARWISE WICHITA, KS	LUST	S101833284 N/A
---------------------------------------	--	-------------	--------------------------

Relative: LUST:
Lower

Facility ID: 80139
 Project Name: DODSON MFG CO
 Project Number: U208700221
 Project Num Extension: Not reported
 Quarter Fraction of Section: Not reported
 Section, Township, Range: Not reported
 Buried Tank Leak Assessment Date: 12/26/1989
 Initial Report Date: 12/26/1989

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

DODSON MFG CO, WICHITA (Continued)

EDR ID Number
 EPA ID Number

Database(s)

S101833284

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

N61
 NNE
 > 1
 7720 ft.

**COLEMAN CO INC NORTHEAST THE
 3600 N HYDRAULIC
 WICHITA, KS 67219**

LUST 1000205872
 67201THCLM36

Site 1 of 2 in cluster N

Relative:
 Higher

Actual:
 1318 ft.

LUST:

Facility ID: 23854
 Project Name: COLEMAN PLANT
 Project Number: U208700244
 Project Num Extension: Not reported
 Quarter Fraction of Section: SENWNW
 Section, Township, Range: 2601E34
 Buried Tank Leak Assessment Date: 10/23/1989
 Initial Report Date: 07/20/1989
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

N62
 NNE
 > 1
 7720 ft.

**BUCKELY ROOFING CO
 3601 N HYDRAULIC
 WICHITA, KS 67219**

LUST S103927104
 N/A

Site 2 of 2 in cluster N

Relative:
 Higher

Actual:
 1318 ft.

LUST:

Facility ID: 25554
 Project Name: BUCKLEY ROOFING CO
 Project Number: U208712499
 Project Num Extension: Not reported
 Quarter Fraction of Section: NESENE
 Section, Township, Range: 2601E33
 Buried Tank Leak Assessment Date: 04/07/1999
 Initial Report Date: 04/06/1999
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

63
 East
 > 1
 7786 ft.

**USD 259, MUELLER
 2821 E 24TH ST. N.
 WICHITA, KS 67219**

LUST S102406742
 N/A

Relative:
 Higher

Actual:
 1367 ft.

LUST:

Facility ID: 08927
 Project Name: USD 259, MUELLER
 Project Number: U208700498
 Project Num Extension: Not reported
 Quarter Fraction of Section: SENWSE
 Section, Township, Range: 2701E03
 Buried Tank Leak Assessment Date: 08/24/1990
 Initial Report Date: 08/16/1990
 Facility Status: HOLD - A 'Hold' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state but because of circumstances at the site, the state does not require that additional remedial work be performed at this time. As the circumstances may change, the state may then re-assign the site a different status.

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

USD 259, MUELLER (Continued)

Database(s) EDR ID Number
 EPA ID Number

S102406742

64 **AMERICAN PRIDE CAR WASH**
WSW **1618 W 21ST**
> 1 **WICHITA, KS 67203**
7878 ft.

LUST **S101837920**
N/A

Relative:
Higher

LUST:

Facility ID: 26515
 Project Name: AMERICAN PRIDE CAR WASH
 Project Number: U208710355
 Project Num Extension: Not reported
 Quarter Fraction of Section: SWSWSWSE
 Section, Township, Range: 2701E05
 Buried Tank Leak Assessment Date: 05/05/1995
 Initial Report Date: 05/03/1995

Actual:
1312 ft.

Facility Status: **MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.**

65 **LOVE BOX CO INC**
North **700 E 37TH ST N**
> 1 **WICHITA, KS 67219**
8017 ft.

LUST **1000195534**
KSD007240740

Relative:
Higher

LUST:

Facility ID: 04406
 Project Name: LOVE BOX CO
 Project Number: U208700703
 Project Num Extension: Not reported
 Quarter Fraction of Section: SWSW
 Section, Township, Range: 2601E28
 Buried Tank Leak Assessment Date: 11/21/1989
 Initial Report Date: 11/07/1989

Actual:
1327 ft.

Facility Status: **CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.**

Facility ID: 04406
 Project Name: LOVE BOX CO
 Project Number: U208711710
 Project Num Extension: Not reported
 Quarter Fraction of Section: NWSWSESW
 Section, Township, Range: 2601E28
 Buried Tank Leak Assessment Date: 09/30/1997
 Initial Report Date: 09/18/1997

Facility Status: **CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.**

Facility ID: 14360
 Project Name: LOVE BOX CO.
 Project Number: U208710440
 Project Num Extension: Not reported
 Quarter Fraction of Section: SWNENW
 Section, Township, Range: 2601E33
 Buried Tank Leak Assessment Date: 06/13/1995
 Initial Report Date: 06/07/1995

Facility Status: **MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.**

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

Database(s) EDR ID Number
 EPA ID Number

LOVE BOX CO INC (Continued)

1000195534

66 YORK UNITARY PRODUCTS GROUP
 North 801 E 37TH ST N
 > 1 WICHITA, KS 67219
 8017 ft.

LUST 1000205870
 67219THCLM80

Relative: LUST:
Higher Facility ID: 25545
 Project Name: EVCON INDUSTRIES
Actual: Project Number: U208700902
 1332 ft. Project Num Extension: A
 Quarter Fraction of Section: NENW
 Section, Township, Range: 2601E33
 Buried Tank Leak Assessment Date: 04/09/1992
 Initial Report Date: 07/03/1991
 Facility Status: ACTIVE - An 'Active' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state. Active sites require that additional remedial work be completed to bring the site into compliance with state and federal law.

Facility ID: 25545
 Project Name: EVCON INDUSTRIES
 Project Number: U208700902
 Project Num Extension: B
 Quarter Fraction of Section: SESEENW
 Section, Township, Range: 2601E33
 Buried Tank Leak Assessment Date: 10/15/1993
 Initial Report Date: 07/20/1993
 Facility Status: ACTIVE - An 'Active' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state. Active sites require that additional remedial work be completed to bring the site into compliance with state and federal law.

67 MOO TO YOU INC
 South 1401 N MOSLEY
 > 1 WICHITA, KS 67219
 8114 ft.

LUST U000718259
 N/A

Relative: LUST:
Lower Facility ID: 08943
 Project Name: MOO TO YOU (KLEPPER CORNER STORE)
Actual: Project Number: U208701277
 1303 ft. Project Num Extension: Not reported
 Quarter Fraction of Section: SWSESESW
 Section, Township, Range: 2701E09
 Buried Tank Leak Assessment Date: 02/01/1994
 Initial Report Date: 10/13/1993
 Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EPA ID Number
			EPA ID Number

68	ROCK MOTOR COURT	LUST	S103370584
North	3801 N BROADWAY		N/A
> 1	WICHITA, KS 67219		
8138 ft.			

Relative: LUST:
Higher

Facility ID: 81629
Project Name: ROCK MOTOR COURT
Project Number: U208712072
Project Num Extension: Not reported
Quarter Fraction of Section: SESESESE
Section, Township, Range: 2601E29
Buried Tank Leak Assessment Date: 07/27/1998
Initial Report Date: 07/27/1998
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

69	H J BORN STONE	LUST	S101833496
NW	901 W 35TH ST		N/A
> 1	WICHITA, KS 67204		
8187 ft.			

Relative: LUST:
Higher

Facility ID: 80080
Project Name: H J BORN STONE
Project Number: U208700633
Project Num Extension: Not reported
Quarter Fraction of Section: Not reported
Section, Township, Range: Not reported
Buried Tank Leak Assessment Date: 01/22/1991
Initial Report Date: 01/22/1991
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

70	200 W 37TH ST N	LUST	S104105115
NNW	WICHITA, KS 67204		N/A
> 1			
8269 ft.			

Relative: LUST:
Higher

Facility ID: 27643
Project Name: FROMM, ROBERT
Project Number: U208700125
Project Num Extension: Not reported
Quarter Fraction of Section: SWSESE
Section, Township, Range: 2601E29
Buried Tank Leak Assessment Date: 12/23/1988
Initial Report Date: 12/22/1988
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

71 SE > 1 8374 ft.	ISELY ALTERNATIVE SCHOOL 2500 E 18TH WICHITA, KS	LUST	S102406646 N/A
-----------------------------	---	------	-------------------

Relative: Higher

Actual: 1316 ft.

LUST:

Facility ID:	08918
Project Name:	ISELY ALTERNATIVE
Project Number:	U208700120
Project Num Extension:	Not reported
Quarter Fraction of Section:	NWSWNE
Section, Township, Range:	2701E10
Buried Tank Leak Assessment Date:	12/20/1988
Initial Report Date:	12/19/1988

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

72 ESE > 1 8504 ft.	21ST & MAPLEWOOD CONTAM, WICHITA 21ST / MAPLEWOOD WICHITA, KS 67214	LUST	S101833755 N/A
------------------------------	--	------	-------------------

Relative: Higher

Actual: 1347 ft.

LUST:

Facility ID:	80136
Project Name:	21ST & MAPLEWOOD CONTAM, WICHITA
Project Number:	U208701093
Project Num Extension:	Not reported
Quarter Fraction of Section:	NWNENE
Section, Township, Range:	2701E10
Buried Tank Leak Assessment Date:	01/13/1992
Initial Report Date:	10/02/1992

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

073 North > 1 8548 ft.	MEL HAMBELTON FORD INC. 3901 N BROADWAY WICHITA, KS 67219	LUST	S101833515 N/A
---------------------------------	--	------	-------------------

Site 1 of 2 in cluster O

Relative: Higher

Actual: 1326 ft.

LUST:

Facility ID:	80056
Project Name:	HAMBELTON FORD INC
Project Number:	U208700679
Project Num Extension:	Not reported
Quarter Fraction of Section:	NESESE
Section, Township, Range:	2601E29
Buried Tank Leak Assessment Date:	03/21/1991
Initial Report Date:	02/07/1990

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

P74	SQUIRES SERVICE	LUST	S101838121
SSW	302 W 13TH STREET		N/A
> 1	WICHITA, KS 67203		

8550 ft.

Site 1 of 2 in cluster P

Relative:
Lower

LUST:

Facility ID: 00531
 Project Name: SQUIRES SERVICE
 Project Number: U208700623
 Project Num Extension: Not reported
 Quarter Fraction of Section: SESWSE
 Section, Township, Range: 2701E08
 Buried Tank Leak Assessment Date: 12/06/1990
 Initial Report Date: 12/05/1990
 Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

Facility ID: 00531
 Project Name: SQURIES
 Project Number: U208711288
 Project Num Extension: Not reported
 Quarter Fraction of Section: SESWSE
 Section, Township, Range: 2701E08
 Buried Tank Leak Assessment Date: 10/03/1995
 Initial Report Date: 10/03/1995
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

75	WICHITA PUBLIC WORKS, NE STATION	LUST	S103370335
NE	2901 E 33RD ST N		N/A
> 1	WICHITA, KS 67202		

8620 ft.

Relative:
Higher

LUST:

Facility ID: 09183
 Project Name: WICHITA PUBLIC WORKS, NE SUBSTATION
 Project Number: U208700312
 Project Num Extension: A
 Quarter Fraction of Section: NESE
 Section, Township, Range: 2601E34
 Buried Tank Leak Assessment Date: 01/25/1990
 Initial Report Date: 01/25/1990
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 09183
 Project Name: WICHITA PUBLIC WORKS, NE SUBSTATION
 Project Number: U208700312
 Project Num Extension: B
 Quarter Fraction of Section: NENWNESE
 Section, Township, Range: 2601E34
 Buried Tank Leak Assessment Date: 12/08/1993
 Initial Report Date: 12/06/1993
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 09183
 Project Name: WICHITA PUBLIC WORKS, NE SUBSTATION
 Project Number: U208711955

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

WICHITA PUBLIC WORKS, NE STATION (Continued)

EDR ID Number
EPA ID Number

Database(s)

S103370335

Project Num Extension: Not reported
Quarter Fraction of Section: NWNESESE
Section, Township, Range: 2601E34
Buried Tank Leak Assessment Date: 04/30/1998
Initial Report Date: 04/08/1998
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

P76
SSW
> 1
8640 ft.

QUIK TRIP #357
1406 N WACO
WICHITA, KS 67203

LUST S102406880
N/A

Site 2 of 2 in cluster P

Relative:
Lower

Actual:
1303 ft.

LUST:
Facility ID: 07289
Project Name: QUIK TRIP #357
Project Number: U208710751
Project Num Extension: Not reported
Quarter Fraction of Section: SESWSE
Section, Township, Range: 2701E08
Buried Tank Leak Assessment Date: 01/02/1996
Initial Report Date: 11/21/1995
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

Q77
SSW
> 1
8663 ft.

NORTH HIGH SCHOOL
1437 ROCHESTER
WICHITA, KS 67203

LUST U000716687
N/A

Site 1 of 2 in cluster Q

Relative:
Lower

Actual:
1305 ft.

LUST:
Facility ID: 08880
Project Name: USD 259, N HIGH SCHOOL
Project Number: U208700293
Project Num Extension: Not reported
Quarter Fraction of Section: Not reported
Section, Township, Range: Not reported
Buried Tank Leak Assessment Date: 01/04/1990
Initial Report Date: 11/16/1989
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 08880
Project Name: USD 259, N HIGH SCHOOL
Project Number: U208700524
Project Num Extension: Not reported
Quarter Fraction of Section: SESESW
Section, Township, Range: 2701E08
Buried Tank Leak Assessment Date: 09/27/1990
Initial Report Date: 09/26/1990
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 08880

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

NORTH HIGH SCHOOL (Continued)

EDR ID Number
EPA ID Number

Database(s)

U000716687

Project Name: USD 259, N HIGH SCHOOL
Project Number: U208711092
Project Num Extension: Not reported
Quarter Fraction of Section: NWSWSESE
Section, Township, Range: 2701E08
Buried Tank Leak Assessment Date: 07/02/1996
Initial Report Date: 07/02/1996
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

078
North
> 1
8689 ft.

T & E OIL #11
3935 N BROADWAY
WICHITA, KS 67219

LUST U003114506
N/A

Site 2 of 2 in cluster O

Relative:
Higher

Actual:
1328 ft.

LUST:
Facility ID: 06835
Project Name: T & E OIL #11
Project Number: U208711161
Project Num Extension: Not reported
Quarter Fraction of Section: NWNESESE
Section, Township, Range: 2601E29
Buried Tank Leak Assessment Date: 10/03/1996
Initial Report Date: 10/03/1996
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

Facility ID: 06835
Project Name: T & E #11
Project Number: U208711706
Project Num Extension: Not reported
Quarter Fraction of Section: NWNESESE
Section, Township, Range: 2601E29
Buried Tank Leak Assessment Date: 09/30/1997
Initial Report Date: 08/06/1997
Facility Status: ACTIVE - An 'Active' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state. Active sites require that additional remedial work be completed to bring the site into compliance with state and federal law.

79
WSW
> 1
8831 ft.

SEARS STORE #2201
1801 W 21ST
WICHITA, KS 67203

LUST S101833863
N/A

Relative:
Higher

Actual:
1312 ft.

LUST:
Facility ID: 28827
Project Name: SEARS #2201
Project Number: U208701298
Project Num Extension: Not reported
Quarter Fraction of Section: SWSWSE
Section, Township, Range: 2701E06
Buried Tank Leak Assessment Date: 01/31/1994
Initial Report Date: 03/01/1994
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

SEARS STORE #2201 (Continued)

S101833863

80 WSW > 1 8889 ft.	TWIN LAKES APTS. 1945 PORTER WICHITA, KS 67202	LUST	S101833558 N/A
---	---	-------------	---------------------------------

Relative:
Higher

LUST:

Facility ID:	80039
Project Name:	TWIN LAKES APT
Project Number:	U208700751
Project Num Extension:	Not reported
Quarter Fraction of Section:	SWSWNE
Section, Township, Range:	2701E07
Buried Tank Leak Assessment Date:	09/10/1991
Initial Report Date:	09/09/1991

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Q81 SSW > 1 8894 ft.	COASTAL MART #9179 527 W 13TH WICHITA, KS 67203	LUST	S102406882 N/A
--	--	-------------	---------------------------------

Relative:
Higher

Site 2 of 2 in cluster Q

LUST:

Facility ID:	07230
Project Name:	COASTAL MART #9179
Project Number:	U208710761
Project Num Extension:	Not reported
Quarter Fraction of Section:	NWNWNWNE
Section, Township, Range:	2701E17
Buried Tank Leak Assessment Date:	12/19/1995
Initial Report Date:	12/18/1995

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

82 SE > 1 9141 ft.	WICHITA FIRE STATION #10 1655 N GROVE WICHITA, KS 67214	LUST	S102406851 N/A
--	--	-------------	---------------------------------

Relative:
Equal

LUST:

Facility ID:	09168
Project Name:	FIRE STATION #10, WICHITA
Project Number:	U208701225
Project Num Extension:	Not reported
Quarter Fraction of Section:	NENENESW
Section, Township, Range:	2701E10
Buried Tank Leak Assessment Date:	09/03/1993
Initial Report Date:	08/23/1993

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

83 **USD 259, SCHOOL SERVICE CENTER**
NNE **3850 N HYDRAULIC**
> 1 **WICHITA, KS 67219**
9211 ft.

LUST **S101833774**
N/A

Relative: LUST:
Higher

Facility ID: 08877
Project Name: USD 259, SCHOOL SERVICE CENTER, WICHITA
Project Number: U208701136
Project Num Extension: A
Quarter Fraction of Section: SWNESWSW
Section, Township, Range: 2601E27
Buried Tank Leak Assessment Date: 03/22/1993
Initial Report Date: 10/27/1992
Facility Status: **ACTIVE** - An 'Active' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state. Active sites require that additional remedial work be completed to bring the site into compliance with state and federal law.

Actual:
1329 ft.

Facility ID: 08877
Project Name: USD 259, SCHOOL SERVICE CENTER, WICHITA
Project Number: U208701136
Project Num Extension: B
Quarter Fraction of Section: NWNESWSW
Section, Township, Range: 2601E27
Buried Tank Leak Assessment Date: 09/28/1993
Initial Report Date: 11/09/1993
Facility Status: **CLOSED** - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 08877
Project Name: USD 259, SCHOOL SERVICE CENTER, WICHITA
Project Number: U208701136
Project Num Extension: C
Quarter Fraction of Section: NWNESWSW
Section, Township, Range: 2601E27
Buried Tank Leak Assessment Date: 05/22/1995
Initial Report Date: 05/17/1995
Facility Status: **CLOSED** - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

R84 **NOORI CONVENIENCE STORE**
East **2601 N. HILLSIDE**
> 1 **WICHITA, KS 67219**
9239 ft.

LUST **U000871964**
N/A

Relative: **Site 1 of 2 in cluster R**
Higher

LUST:
Facility ID: 11699
Project Name: BETCO
Project Number: U208712479
Project Num Extension: Not reported
Quarter Fraction of Section: SESESENE
Section, Township, Range: 2701E03
Buried Tank Leak Assessment Date: 04/07/1999
Initial Report Date: 12/03/1998
Facility Status: **MONITOR** - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

NOORI CONVENIENCE STORE (Continued)

U000871964

**R85
East
> 1
9244 ft.**

**MART 74
2545 N. HILLSIDE
WICHITA, KS 67214**

**LUST U000199163
N/A**

Site 2 of 2 in cluster R

**Relative:
Higher**

LUST:

**Actual:
1374 ft.**

Facility ID: 29054
Project Name: MART 74 (NOW BOWDEN LIQUOR)
Project Number: U208700615
Project Num Extension: Not reported
Quarter Fraction of Section: NENENE
Section, Township, Range: 2701E03
Buried Tank Leak Assessment Date: 12/19/1990
Initial Report Date: 12/19/1990
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

**86
East
> 1
9251 ft.**

**BAKER DRYWALL & CONST.
2652 N HILLSIDE
WICHITA, KS 67219**

**LUST S102406697
N/A**

**Relative:
Higher**

LUST:

**Actual:
1369 ft.**

Facility ID: 80104
Project Name: BAKER DRYWALL
Project Number: U208700347
Project Num Extension: Not reported
Quarter Fraction of Section: Not reported
Section, Township, Range: Not reported
Buried Tank Leak Assessment Date: 02/22/1990
Initial Report Date: 02/22/1990
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

**87
SSW
> 1
9254 ft.**

**TAILORED JEWELLERY
715 W 13TH ST
WICHITA, KS 67203**

**LUST S105434772
N/A**

**Relative:
Lower**

LUST:

**Actual:
1280 ft.**

Facility ID: 88888
Project Name: TAILORED JEWELRY
Project Number: U208701151
Project Num Extension: Not reported
Quarter Fraction of Section: NWNENW
Section, Township, Range: 2701E17
Buried Tank Leak Assessment Date: 05/10/1993
Initial Report Date: 05/07/1993
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	

88 East > 1 9267 ft.	WICHITA PARK CEMETARY SHOP 2489 N HILLSIDE WICHITA, KS 67208	LUST	S101833604 N/A
--------------------------------------	---	-------------	--------------------------

Relative: Higher	LUST: Facility ID: 80009 Project Name: WICHITA PARK CEMETARY Project Number: U208700831 Project Num Extension: Not reported Quarter Fraction of Section: NWSWSW Section, Township, Range: 2701E02 Buried Tank Leak Assessment Date: 12/17/1991 Initial Report Date: 12/17/1991 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.		
Actual: 1372 ft.			

89 West > 1 9278 ft.	PHILLIPS 66, AMIDON 2600 AMIDON WICHITA, KS 67204	LUST	S103927102 N/A
--------------------------------------	--	-------------	--------------------------

Relative: Higher	LUST: Facility ID: 28685 Project Name: PHILLIPS 66, AMIDON Project Number: U208712495 Project Num Extension: Not reported Quarter Fraction of Section: SWSWSWNE Section, Township, Range: 2701E06 Buried Tank Leak Assessment Date: 04/02/1999 Initial Report Date: 03/31/1999 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.		
Actual: 1314 ft.			

90 West > 1 9307 ft.	CITGO SERVICE STATION 2700 N AMIDON WICHITA, KS 67204	LUST	S103370607 N/A
--------------------------------------	--	-------------	--------------------------

Relative: Higher	LUST: Facility ID: 07225 Project Name: CITGO SERVICE STATION Project Number: U208712110 Project Num Extension: Not reported Quarter Fraction of Section: SWNWSWNE Section, Township, Range: 2701E06 Buried Tank Leak Assessment Date: 10/06/1998 Initial Report Date: 09/09/1998 Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.		
Actual: 1314 ft.			

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EPA ID Number

S91 WSW > 1 9347 ft.	COASTAL MART #9157 1925 W 21ST WICHITA, KS 67203	LUST	S101833564 N/A
--	---	-------------	---------------------------------

Site 1 of 3 in cluster S

Relative: Higher

Actual: 1312 ft.

LUST:

Facility ID: 07220

Project Name: COASTAL MART #9157, WICHITA

Project Number: U208700769

Project Num Extension: Not reported

Quarter Fraction of Section: NWNWNE

Section, Township, Range: 2701E07

Buried Tank Leak Assessment Date: 10/07/1991

Initial Report Date: 10/04/1991

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

92 SSW > 1 9488 ft.	GENE'S 66 801 W 13TH WICHITA, KS 67203	LUST	S101833618 N/A
---	---	-------------	---------------------------------

Relative: Equal

Actual: 1310 ft.

LUST:

Facility ID: 07017

Project Name: GENES 66

Project Number: U208700853

Project Num Extension: Not reported

Quarter Fraction of Section: SWSESW

Section, Township, Range: 2701E08

Buried Tank Leak Assessment Date: 01/03/1992

Initial Report Date: 01/02/1992

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

S93 WSW > 1 9489 ft.	FINA #9500 2265 N AMIDON WICHITA, KS 67204	LUST	U003178295 N/A
--	---	-------------	---------------------------------

Site 2 of 3 in cluster S

Relative: Higher

Actual: 1319 ft.

LUST:

Facility ID: 06587

Project Name: FINA #9500, WICHITA

Project Number: U208700396

Project Num Extension: Not reported

Quarter Fraction of Section: SESESW

Section, Township, Range: 2701E06

Buried Tank Leak Assessment Date: 03/25/1992

Initial Report Date: 07/03/1990

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EPA ID Number

94 NNW > 1 9642 ft.	SOUTHWESTERN BELL TELEPHONE CO 3917 N ARKANSAS WICHITA, KS 67204	LUST	U001111828 N/A
---	---	-------------	---------------------------------

Relative: Higher	LUST: Facility ID: 08868 Project Name: SW BELL TELEPHONE Project Number: U208700139 Project Num Extension: Not reported Quarter Fraction of Section: NESESW Section, Township, Range: 2601E29 Buried Tank Leak Assessment Date: 10/23/1989 Initial Report Date: 10/23/1989 Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.		
-----------------------------------	---	--	--

S95 WSW > 1 9658 ft.	AMOCO OIL #7207 2201 AMIDON WICHITA, KS 67204	LUST	S101833362 N/A
--	--	-------------	---------------------------------

Site 3 of 3 in cluster S

Relative: Lower	LUST: Facility ID: 25215 Project Name: AMOCO #7207 Project Number: U208700381 Project Num Extension: Not reported Quarter Fraction of Section: SESESW Section, Township, Range: 2701E06 Buried Tank Leak Assessment Date: 05/27/1992 Initial Report Date: 05/24/1990 Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.		
----------------------------------	---	--	--

96 SW > 1 9690 ft.	USD 259, MASHALL MIDDLE SCHOOL 1510 PAYNE WICHITA, KS 67203	LUST	S101833582 N/A
--	--	-------------	---------------------------------

Relative: Lower	LUST: Facility ID: 08891 Project Name: USD 259, MARSHALL MIDDLE SCHOOL, WICHITA Project Number: U208700790 Project Num Extension: Not reported Quarter Fraction of Section: NESWSW Section, Township, Range: 2701E08 Buried Tank Leak Assessment Date: 09/09/1991 Initial Report Date: 04/04/1991 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.		
----------------------------------	--	--	--

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	

97 ESE > 1 9728 ft.	DANNY'S BURGERS, FORMER 2147 N HILLSIDE WICHITA, KS 67214	LUST	S101833492 N/A
---	--	-------------	---------------------------------

Relative: Higher	LUST: Facility ID: 29046 Project Name: DANNYS BURGERS, FORMER Project Number: U208700627 Project Num Extension: Not reported Quarter Fraction of Section: NENENE Section, Township, Range: 2701E10 Buried Tank Leak Assessment Date: 01/14/1991 Initial Report Date: 09/20/1990 Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.		
-----------------------------------	---	--	--

98 South > 1 9731 ft.	7-ELEVEN #251 1161 N BROADWAY WICHITA, KS 67214	LUST	S102688435 N/A
---	--	-------------	---------------------------------

Relative: Lower	LUST: Facility ID: 27139 Project Name: 7-ELEVEN #251 Project Number: U208701271 Project Num Extension: Not reported Quarter Fraction of Section: NESENE Section, Township, Range: 2701E17 Buried Tank Leak Assessment Date: 12/03/1993 Initial Report Date: 09/23/1993 Facility Status: ACTIVE - An 'Active' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state. Active sites require that additional remedial work be completed to bring the site into compliance with state and federal law.		
----------------------------------	---	--	--

99 WSW > 1 9816 ft.	BANTZ-HAWKINS 2015 W 21ST ST WICHITA, KS 67203	LUST	S101833764 N/A
---	---	-------------	---------------------------------

Relative: Higher	LUST: Facility ID: 11715 Project Name: BANTZ-HAWKINS Project Number: U208701109 Project Num Extension: Not reported Quarter Fraction of Section: NENENENW Section, Township, Range: 2701E07 Buried Tank Leak Assessment Date: 02/11/1993 Initial Report Date: 02/11/1993 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.		
-----------------------------------	--	--	--

MAP FINDINGS

Map ID							
Direction							
Distance							
Distance (ft.)							
Elevation	Site				Database(s)	EDR ID Number	EPA ID Number

100							
NE	2400 E 37TH ST N				LUST	S102282596	N/A
> 1	WICHITA, KS 67219						
9905 ft.							

Relative: Higher LUST:

Facility ID: 80067

Project Name: PHILLIPS PIPELINE

Actual: 1353 ft. Project Number: U208700228

Project Num Extension: Not reported

Quarter Fraction of Section: NWSWNE

Section, Township, Range: 2601E27

Buried Tank Leak Assessment Date: 10/05/1989

Initial Report Date: 10/04/1989

Facility Status: **CLOSED** - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

101							
NE	QUALITY DISTRIBUTORS INC				LUST	S101833688	N/A
> 1	3619 N POPLAR						
10027 ft.	WICHITA, KS 67219						

Relative: Higher LUST:

Facility ID: 28143

Project Name: QUALITY DISTRIBUTORS

Actual: 1346 ft. Project Number: U208700981

Project Num Extension: Not reported

Quarter Fraction of Section: NESWSWNE

Section, Township, Range: 2601E34

Buried Tank Leak Assessment Date: 07/27/1992

Initial Report Date: 04/24/1992

Facility Status: **CLOSED** - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

102							
WNW	PLEASANT VALLEY ELEMENTARY				LUST	U002233242	N/A
> 1	2000 W 29TH ST N						
10304 ft.	WICHITA, KS 67204						

Relative: Higher LUST:

Facility ID: 08933

Project Name: USD 259, PLEASANT VALLEY

Actual: 1323 ft. Project Number: U208711277

Project Num Extension: Not reported

Quarter Fraction of Section: SESW

Section, Township, Range: 2601E31

Buried Tank Leak Assessment Date: 01/19/1990

Initial Report Date: 12/06/1989

Facility Status: **CLOSED** - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 08933

Project Name: USD 259, PLEASANT

Project Number: U208700299

Project Num Extension: Not reported

Quarter Fraction of Section: SWSESW

Section, Township, Range: 2601E31

Buried Tank Leak Assessment Date: 05/03/1991

Initial Report Date: 04/10/1991

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

EDR ID Number
 EPA ID Number

PLEASANT VALLEY ELEMENTARY (Continued)

U002233242

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

**103
 SSW
 > 1
 10382 ft.**

**CENTRAL STEEL INC
 240 W 10TH ST
 WICHITA, KS 67203**

**LUST S102407864
 N/A**

**Relative:
 Lower**

LUST:

Facility ID: 81480
 Project Name: CENTRAL STEEL INC
 Project Number: U208711201
 Project Num Extension: Not reported
 Quarter Fraction of Section: SWNWSENE
 Section, Township, Range: 2701E17
 Buried Tank Leak Assessment Date: 10/25/1996
 Initial Report Date: 10/23/1996

**Actual:
 1295 ft.**

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

**104
 South
 > 1
 10387 ft.**

**HOUSE OIL COMPANY
 1055 N MOSLEY
 WICHITA, KS 67214**

**LUST U000195748
 N/A**

**Relative:
 Lower**

LUST:

Facility ID: 02992
 Project Name: HOUSE OIL
 Project Number: U208700525
 Project Num Extension: Not reported
 Quarter Fraction of Section: SESENW
 Section, Township, Range: 2701E16
 Buried Tank Leak Assessment Date: 10/04/1990
 Initial Report Date: 10/01/1990

**Actual:
 1299 ft.**

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

**T105
 SE
 > 1
 10388 ft.**

**LOFGREN BURKE PROPERTY
 2403 E 13TH STREET
 WICHITA, KS 67208**

**LUST S102406760
 N/A**

Site 1 of 2 in cluster T

**Relative:
 Lower**

LUST:

Facility ID: 29166
 Project Name: BURKE, LOFGREN
 Project Number: U208700664
 Project Num Extension: Not reported
 Quarter Fraction of Section: NWNWNE
 Section, Township, Range: 2701E15
 Buried Tank Leak Assessment Date: 03/04/1991
 Initial Report Date: 03/01/1991

**Actual:
 1305 ft.**

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

MAP FINDINGS

Map ID							
Direction							
Distance							
Distance (ft.)							
Elevation	Site				Database(s)		EDR ID Number
							EPA ID Number

LOFGREN BURKE PROPERTY (Continued)

S102406760

106 ESE > 1 10470 ft.	QUIRING MORUARY 3425 E 21ST WICHITA, KS 67208	LUST	S101833603 N/A
---	--	-------------	---------------------------------

Relative: Higher	LUST:	
Actual: 1372 ft.	Facility ID: 07722 Project Name: QUIRING MORTURARY Project Number: U208700830 Project Num Extension: Not reported Quarter Fraction of Section: SWSWSW Section, Township, Range: 2701E02 Buried Tank Leak Assessment Date: 12/17/1991 Initial Report Date: 12/17/1991 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.	

T107 SE > 1 10599 ft.	G&L GARAGE 2502 E 13TH WICHITA, KS 67214	LUST	S101833728 N/A
---	---	-------------	---------------------------------

	Site 2 of 2 in cluster T	
Relative: Lower	LUST:	
Actual: 1304 ft.	Facility ID: 00485 Project Name: G&L GARAGE Project Number: U208701043 Project Num Extension: Not reported Quarter Fraction of Section: SESESESW Section, Township, Range: 2701E10 Buried Tank Leak Assessment Date: 10/23/1992 Initial Report Date: Not reported Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.	

108 West > 1 10624 ft.	MCLEAN ELEMENTARY SCHOOL 2277 MARIGOLD WICHITA, KS 67204	LUST	U000871770 N/A
--	---	-------------	---------------------------------

Relative: Higher	LUST:	
Actual: 1313 ft.	Facility ID: 08926 Project Name: USD 259, MCLEAN ELEMENTARY Project Number: U208700442 Project Num Extension: Not reported Quarter Fraction of Section: SWSW Section, Township, Range: 2701E06 Buried Tank Leak Assessment Date: 06/14/1990 Initial Report Date: 06/07/1990 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.	

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EPA ID Number

U109 South > 1 10745 ft.	ST FRANCIS REG MEDICAL CENTER 624 E 9TH WICHITA, KS 67214 Site 1 of 2 in cluster U	LUST	S103236721 N/A
--	--	-------------	--------------------------

Relative:
Lower

LUST:

Facility ID: 26995
 Project Name: ST FRANCIS REG MED CTR
 Project Number: U208700975
 Project Num Extension: Not reported
 Quarter Fraction of Section: SWSESWNW
 Section, Township, Range: 2701E16
 Buried Tank Leak Assessment Date: 06/29/1992
 Initial Report Date: 06/24/1992
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

110 East > 1 10767 ft.	BUCKNER ELEMENTARY SCHOOL 3530 E 27TH NORTH WICHITA, KS 67220	LUST	U000871758 N/A
--	--	-------------	--------------------------

Relative:
Higher

LUST:

Facility ID: 08903
 Project Name: USD 259, BUCKNER ELEMENTARY
 Project Number: U208700435
 Project Num Extension: Not reported
 Quarter Fraction of Section: NENW
 Section, Township, Range: 2701E02
 Buried Tank Leak Assessment Date: 05/08/1990
 Initial Report Date: 05/03/1990
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

111 WSW > 1 10847 ft.	QWIKSTOP 2143 W 21ST WICHITA, KS 67203	LUST	S105434766 N/A
---------------------------------------	---	-------------	--------------------------

Relative:
Higher

LUST:

Facility ID: 88888
 Project Name: QWIKSTOP
 Project Number: U208700682
 Project Num Extension: Not reported
 Quarter Fraction of Section: NWNENW
 Section, Township, Range: 2701E07
 Buried Tank Leak Assessment Date: 04/16/1991
 Initial Report Date: 04/15/1991
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

U112 South > 1 10927 ft.	ST FRANCIS REGIONAL MED CENTER 929 N ST FRANCIS WICHITA, KS 67214	LUST	S104105116 N/A
--	--	-------------	--------------------------

Site 2 of 2 in cluster U

Relative: Lower

Actual: 1296 ft.

LUST:

Facility ID:	06261
Project Name:	ST FRANCIS REG MED CTR
Project Number:	U208700868
Project Num Extension:	Not reported
Quarter Fraction of Section:	SESWNW
Section, Township, Range:	2701E16
Buried Tank Leak Assessment Date:	01/31/1992
Initial Report Date:	01/30/1992
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

113 WNW > 1 10997 ft.	USD 259, PLEASANT VALLEY MIDDLE 2220 W 29TH N WICHITA, KS 67204	LUST	S101833552 N/A
---------------------------------------	--	-------------	--------------------------

Relative: Higher

Actual: 1320 ft.

LUST:

Facility ID:	08894
Project Name:	USD 259, PLEASANT VALLEY
Project Number:	U208700742
Project Num Extension:	Not reported
Quarter Fraction of Section:	SESWSW
Section, Township, Range:	2601E31
Buried Tank Leak Assessment Date:	07/11/1991
Initial Report Date:	07/10/1991
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

114 ESE > 1 11083 ft.	TOTAL #1850, WICHITA 1680 N HILLSIDE WICHITA, KS 67208	LUST	S101838042 N/A
---------------------------------------	---	-------------	--------------------------

Relative: Higher

Actual: 1372 ft.

LUST:

Facility ID:	06962
Project Name:	TOTAL #1850
Project Number:	U208710494
Project Num Extension:	Not reported
Quarter Fraction of Section:	SWNWSW
Section, Township, Range:	2701E11
Buried Tank Leak Assessment Date:	07/28/1995
Initial Report Date:	07/26/1995
Facility Status:	ACTIVE - An 'Active' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state. Active sites require that additional remedial work be completed to bring the site into compliance with state and federal law.

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	

115	WSU		LUST
ESE	1845 FAIRMOUNT		S101833244
> 1	WICHITA, KS		N/A
11156 ft.			

Relative: LUST:
Higher

Actual:
1405 ft.

Facility ID: 24212
 Project Name: WSU, CAC
 Project Number: U208700169
 Project Num Extension: Not reported
 Quarter Fraction of Section: Not reported
 Section, Township, Range: Not reported
 Buried Tank Leak Assessment Date: 11/15/1989
 Initial Report Date: 11/15/1989
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 24212
 Project Name: WSU, FAIRMOUNT TOWERS
 Project Number: U208700170
 Project Num Extension: Not reported
 Quarter Fraction of Section: Not reported
 Section, Township, Range: Not reported
 Buried Tank Leak Assessment Date: 11/15/1989
 Initial Report Date: 11/15/1989
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 24212
 Project Name: WSU, ANLBERG
 Project Number: U208700172
 Project Num Extension: Not reported
 Quarter Fraction of Section: Not reported
 Section, Township, Range: Not reported
 Buried Tank Leak Assessment Date: 11/15/1989
 Initial Report Date: 11/15/1989
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 24212
 Project Name: WSU, DFAC
 Project Number: U208700173
 Project Num Extension: Not reported
 Quarter Fraction of Section: Not reported
 Section, Township, Range: Not reported
 Buried Tank Leak Assessment Date: 11/15/1989
 Initial Report Date: 11/15/1989
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 24212
 Project Name: WSU, BRENNAN
 Project Number: U208700575
 Project Num Extension: Not reported
 Quarter Fraction of Section: Not reported
 Section, Township, Range: Not reported
 Buried Tank Leak Assessment Date: 11/15/1989
 Initial Report Date: 11/15/1989

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WSU (Continued)

S101833244

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 24212
Project Name: WSU, HENRY LE
Project Number: U208700576
Project Num Extension: Not reported
Quarter Fraction of Section: Not reported
Section, Township, Range: Not reported
Buried Tank Leak Assessment Date: 11/15/1989
Initial Report Date: 11/15/1989

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 24212
Project Name: WSU, OLD PHYSICAL
Project Number: U208700579
Project Num Extension: Not reported
Quarter Fraction of Section: Not reported
Section, Township, Range: Not reported
Buried Tank Leak Assessment Date: 11/15/1989
Initial Report Date: 11/15/1989

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 24212
Project Name: WSU, WIND TUNNEL
Project Number: U208700624
Project Num Extension: Not reported
Quarter Fraction of Section: Not reported
Section, Township, Range: Not reported
Buried Tank Leak Assessment Date: 11/15/1989
Initial Report Date: 11/15/1989

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 24212
Project Name: WSU, GRACE WILKIE HALL
Project Number: U208700625
Project Num Extension: Not reported
Quarter Fraction of Section: Not reported
Section, Township, Range: Not reported
Buried Tank Leak Assessment Date: 11/15/1989
Initial Report Date: 11/15/1989

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 24212
Project Name: WSU, CENTRAL POWER PLANT
Project Number: U208711734
Project Num Extension: Not reported
Quarter Fraction of Section: Not reported
Section, Township, Range: Not reported
Buried Tank Leak Assessment Date: 10/27/1997
Initial Report Date: 10/27/1997

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

U-STORE-IT (Continued)

S101833735

Buried Tank Leak Assessment Date: 11/10/1992
Initial Report Date: 11/10/1992
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

V119
South
> 1
11708 ft.

WICHITA PUBLIC SCALES
811 N MOSLEY
WICHITA, KS 67214

LUST S102406763
N/A

Site 1 of 2 in cluster V

Relative:
Lower

LUST:

Actual:
1300 ft.

Facility ID: 80010
Project Name: WICHITA PUBLIC SCALES
Project Number: U208700702
Project Num Extension: Not reported
Quarter Fraction of Section: NESW
Section, Township, Range: 2701E16
Buried Tank Leak Assessment Date: 12/07/1989
Initial Report Date: 11/20/1989
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

120
SSE
> 1
11720 ft.

CITY-COUNTY HEALTH DEPT.
1900 E 9TH
WICHITA, KS 67214

LUST S102406716
N/A

Relative:
Lower

LUST:

Actual:
1299 ft.

Facility ID: 09181
Project Name: WICHITA/SEDGWICK CO HEALTH
Project Number: U208700430
Project Num Extension: Not reported
Quarter Fraction of Section: SWNWNE
Section, Township, Range: 2701E15
Buried Tank Leak Assessment Date: 05/15/1990
Initial Report Date: 05/15/1990
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

121
SW
> 1
11820 ft.

TOWN & COUNTRY #28
1826 W 13TH
WICHITA, KS 67203

LUST S101833817
N/A

Relative:
Higher

LUST:

Actual:
1314 ft.

Facility ID: 06965
Project Name: TOWN & COUNTRY #28
Project Number: U208701209
Project Num Extension: Not reported
Quarter Fraction of Section: SESWSWSE
Section, Township, Range: 2701E07
Buried Tank Leak Assessment Date: 08/06/1993
Initial Report Date: 04/30/1993
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EPA ID Number

TOWN & COUNTRY #28 (Continued)

S101833817

122	OK TRANSFER	LUST	S101833768
South	811 E MURDOCK		N/A
> 1	WICHITA, KS 67214		
11893 ft.			

Relative:
Lower

LUST:

Facility ID:	08640	
Project Name:	OK TRANSFER	
Project Number:	U208701117	
Project Num Extension:	Not reported	
Quarter Fraction of Section:	SWSENESE	
Section, Township, Range:	2701E16	
Buried Tank Leak Assessment Date:	03/02/1993	
Initial Report Date:	03/02/1993	
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.	

V123	MERCURY ELECTRIC INC	LUST	U000874387
South	1004 E MURDOCK		N/A
> 1	WICHITA, KS 67214		
11947 ft.			

Relative:
Lower

Site 2 of 2 in cluster V

LUST:

Facility ID:	29231	
Project Name:	MERCURY ELECTRIC	
Project Number:	U208701119	
Project Num Extension:	Not reported	
Quarter Fraction of Section:	SWSWNWSE	
Section, Township, Range:	2701E16	
Buried Tank Leak Assessment Date:	03/09/1993	
Initial Report Date:	03/08/1993	
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.	

124	TOWN & COUNTRY #16	LUST	S101833800
South	803 N BROADWAY		N/A
> 1	WICHITA, KS 67214		
11952 ft.			

Relative:
Lower

LUST:

Facility ID:	06956	
Project Name:	TOWN & COUNTRY #16	
Project Number:	U208701178	
Project Num Extension:	Not reported	
Quarter Fraction of Section:	SENESE	
Section, Township, Range:	2701E17	
Buried Tank Leak Assessment Date:	07/13/1993	
Initial Report Date:	04/27/1993	
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.	

MAP FINDINGS

Map ID Direction Distance Distance (ft.) Elevation	Site	Database(s)	EDR ID Number EPA ID Number
--	------	-------------	--------------------------------

125 South > 1 11986 ft.	ST FRANCIS REGIONAL MED CTR 817 N ST FRANCIS WICHITA, KS 67214	LUST	S102406808 N/A
----------------------------------	---	------	-------------------

Relative: Lower	LUST: Facility ID: 26994 Project Name: ST FRANCIS REG MED CTR Project Number: U208701030 Project Num Extension: Not reported Quarter Fraction of Section: SESENWSW Section, Township, Range: 2701E16 Buried Tank Leak Assessment Date: 10/12/1992 Initial Report Date: 02/29/1992 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.
Actual: 1306 ft.	

126 NE > 1 12153 ft.	KORNER STORE 3800 N HILLSIDE WICHITA, KS 67219	LUST	S102406740 N/A
-------------------------------	---	------	-------------------

Relative: Higher	LUST: Facility ID: 02496 Project Name: KORNER STORE Project Number: U208700487 Project Num Extension: Not reported Quarter Fraction of Section: SWSWSW Section, Township, Range: 2601E26 Buried Tank Leak Assessment Date: 08/07/1990 Initial Report Date: 08/07/1990 Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.
Actual: 1358 ft.	

127 SE > 1 12202 ft.	NAIL AUTO SERVICE INC 1402 N HILLSIDE WICHITA, KS 67208	LUST	U000872245 N/A
-------------------------------	--	------	-------------------

Relative: Higher	LUST: Facility ID: 18118 Project Name: NAIL AUTO SERVICE Project Number: U208701312 Project Num Extension: Not reported Quarter Fraction of Section: SWSWSWSW Section, Township, Range: 2701E11 Buried Tank Leak Assessment Date: 03/29/1994 Initial Report Date: 03/25/1994 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.
Actual: 1360 ft.	

MAP FINDINGS

Map ID	Direction	Distance	Distance (ft.)	Elevation	Site	Database(s)	EDR ID Number	EPA ID Number
128	SSE	> 1	12265 ft.		AT&T, WICHITA 1516 E MURDOCK WICHITA, KS 67214	LUST	S101833605	N/A
Relative:	Lower	LUST:						
		Facility ID: 14748						
		Project Name: AT&T, WICHITA						
Actual:	1301 ft.	Project Number: U208700832						
		Project Num Extension: Not reported						
		Quarter Fraction of Section: SENESE						
		Section, Township, Range: 2701E16						
		Buried Tank Leak Assessment Date: 12/26/1991						
		Initial Report Date: 12/19/1991						
		Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.						
129	South	> 1	12324 ft.		HAHNER, FOREMAN & HARNESS 724 N WABASH WICHITA, KS 67214	LUST	S104105226	N/A
Relative:	Lower	LUST:						
		Facility ID: 03639						
		Project Name: HAHNER, FOREMAN & HARNESS INC						
Actual:	1294 ft.	Project Number: U208712224						
		Project Num Extension: Not reported						
		Quarter Fraction of Section: NWSWSE						
		Section, Township, Range: 2701E16						
		Buried Tank Leak Assessment Date: 12/09/1998						
		Initial Report Date: 12/09/1998						
		Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.						
130	SSE	> 1	12395 ft.		BUCKLEY INDUSTRIES INC 1600 E MURDOCK WICHITA, KS 67214	LUST	S101833473	N/A
Relative:	Lower	LUST:						
		Facility ID: 09488						
		Project Name: BUCKLEY INDUSTRIES						
Actual:	1302 ft.	Project Number: U208700568						
		Project Num Extension: Not reported						
		Quarter Fraction of Section: SENESE						
		Section, Township, Range: 2701E16						
		Buried Tank Leak Assessment Date: 11/03/1989						
		Initial Report Date: 11/02/1989						
		Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.						

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EPA ID Number

W131 SSE > 1 12411 ft.	WICHITA, KING B CLUB 2323 E 9TH WICHITA, KS 67214	LUST	S102406890 N/A
--	--	-------------	--------------------------

Site 1 of 2 in cluster W

Relative:
Lower

LUST:

Facility ID:	81435
Project Name:	KING B CLUB
Project Number:	U208710974
Project Num Extension:	Not reported
Quarter Fraction of Section:	NENENESW
Section, Township, Range:	2701E15
Buried Tank Leak Assessment Date:	05/13/1996
Initial Report Date:	05/09/1996
Facility Status:	MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

X132 South > 1 12412 ft.	WICHITA FIRE STATION # 1 731 N MAIN WICHITA, KS 67213	LUST	S101833642 N/A
--	--	-------------	--------------------------

Site 1 of 2 in cluster X

Relative:
Lower

LUST:

Facility ID:	09160
Project Name:	FIRE STATION #01, WICHITA
Project Number:	U208700906
Project Num Extension:	Not reported
Quarter Fraction of Section:	SEnwSE
Section, Township, Range:	2701E17
Buried Tank Leak Assessment Date:	03/30/1992
Initial Report Date:	08/01/1991
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

X133 South > 1 12532 ft.	AMERICAN RED CROSS BLOOD SERVI 707 N MAIN WICHITA, KS 67203	LUST	U002234016 N/A
--	--	-------------	--------------------------

Site 2 of 2 in cluster X

Relative:
Lower

LUST:

Facility ID:	26849
Project Name:	AMERICAN RED CROSS
Project Number:	U208701363
Project Num Extension:	Not reported
Quarter Fraction of Section:	NENwSESE
Section, Township, Range:	2701E17
Buried Tank Leak Assessment Date:	09/02/1994
Initial Report Date:	09/01/1994
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	

W134 SSE > 1 12539 ft.	JERRY MCCRAY 1001 N. GROVE WICHITA, KS Site 2 of 2 in cluster W	LUST	S105200821 N/A
--	--	-------------	---------------------------------

Relative:
Lower

Actual:
1307 ft.

LUST:

Facility ID: 81828

Project Name: JERRY MCCRAY

Project Number: U208713157

Project Num Extension: Not reported

Quarter Fraction of Section: SESEENW

Section, Township, Range: 2701E15

Buried Tank Leak Assessment Date: 10/26/2001

Initial Report Date: 10/25/2001

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

135 South > 1 12593 ft.	CHRISTOPHER STELL INC. 1220 BLAINE WICHITA, KS 67214	LUST	S101833229 N/A
---	---	-------------	---------------------------------

Relative:
Lower

Actual:
1301 ft.

LUST:

Facility ID: 23923

Project Name: CHRISTOPHER STEEL

Project Number: U208700145

Project Num Extension: Not reported

Quarter Fraction of Section: NESWSE

Section, Township, Range: 2701E12

Buried Tank Leak Assessment Date: 05/10/1989

Initial Report Date: 03/21/1989

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

136 NNW > 1 12725 ft.	4141 N SENECA WICHITA, KS 67204	LUST	S101833795 N/A
---	--	-------------	---------------------------------

Relative:
Higher

Actual:
1331 ft.

LUST:

Facility ID: 08873

Project Name: USD 259, TRANSPORTATION ED CTR

Project Number: U208701168

Project Num Extension: Not reported

Quarter Fraction of Section: SESESENE

Section, Township, Range: 2601E30

Buried Tank Leak Assessment Date: 05/25/1993

Initial Report Date: 12/04/1992

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EPA ID Number

137	BYRD-SNODGRASS FUNERAL HOME	LUST	S101838213
South	633 N BROADWAY		N/A
> 1	WICHITA, KS 67214		
12786 ft.			

Relative: LUST:
Lower Facility ID: 81384
Project Name: BYRD-SNODGRASS FUNERAL HOME
Actual: Project Number: U208710746
1300 ft. Project Num Extension: Not reported
Quarter Fraction of Section: SENESESE
Section, Township, Range: 2701E17
Buried Tank Leak Assessment Date: 12/28/1995
Initial Report Date: 12/27/1995
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

138	CONTINENTAL BAKING	LUST	S101833265
South	601 NE EMPORIA		N/A
> 1	WICHITA, KS 67214		
12826 ft.			

Relative: LUST:
Lower Facility ID: 06521
Project Name: CONTINENTAL BAKING CO
Actual: Project Number: U208711275
1299 ft. Project Num Extension: Not reported
Quarter Fraction of Section: NWSWSW
Section, Township, Range: 2701E16
Buried Tank Leak Assessment Date: 07/10/1989
Initial Report Date: 07/10/1989
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 06521
Project Name: CONTINENTAL BAKING CO
Project Number: U208700204
Project Num Extension: Not reported
Quarter Fraction of Section: NWSWSW
Section, Township, Range: 2701E16
Buried Tank Leak Assessment Date: 09/04/1990
Initial Report Date: 08/29/1990
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

139	USD 259, EMERSON	LUST	S102599426
WSW	2330 W 15TH		N/A
> 1	WICHITA, KS		
12873 ft.			

Relative: LUST:
Lower Facility ID: 08913
Project Name: USD 259, EMERSON E
Actual: Project Number: U208700406
1304 ft. Project Num Extension: Not reported
Quarter Fraction of Section: Not reported
Section, Township, Range: Not reported
Buried Tank Leak Assessment Date: 04/12/1990
Initial Report Date: 04/12/1990

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

Database(s)
EPA ID Number

EPA ID Number

LUCENT TECHNOLOGIES (Continued)

S102689614

Project Number: U208712933
Project Num Extension: Not reported
Quarter Fraction of Section: SWSWSWSW
Section, Township, Range: 2701E21
Buried Tank Leak Assessment Date: 06/26/2000
Initial Report Date: 06/09/2000
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Z143
South
> 1
13366 ft.

SHIVELY TIRE INC
601 E CENTRAL
WICHITA, KS 67202

LUST U000872326
N/A

Site 2 of 2 in cluster Z

Relative:
Lower

Actual:
1296 ft.

LUST:
Facility ID: 20041
Project Name: SHIVELY TIRE INC
Project Number: U208700399
Project Num Extension: Not reported
Quarter Fraction of Section: NWNENW
Section, Township, Range: 2701E21
Buried Tank Leak Assessment Date: 02/19/1990
Initial Report Date: 02/14/1990
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

AA144
South
> 1
13392 ft.

DOLESE-CENTRAL PLANT
826 E CENTRAL
WICHITA, KS 67202

LUST S101833901
N/A

Site 1 of 3 in cluster AA

Relative:
Lower

Actual:
1295 ft.

LUST:
Facility ID: 25710
Project Name: DOLESE-CENTRAL PLANT
Project Number: U208710118
Project Num Extension: Not reported
Quarter Fraction of Section: NESESESW
Section, Township, Range: 2701E16
Buried Tank Leak Assessment Date: 01/17/1995
Initial Report Date: 01/17/1994
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

AA145
South
> 1
13398 ft.

JOY, KEITH (ABANDONED FACILITY)
920 E CENTRAL
WICHITA, KS 67202

LUST S101833410
N/A

Site 2 of 3 in cluster AA

Relative:
Lower

Actual:
1295 ft.

LUST:
Facility ID: 80091
Project Name: JOY, KEITH
Project Number: U208700465
Project Num Extension: Not reported
Quarter Fraction of Section: SESESESW

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

JOY, KEITH (ABANDONED FACILITY) (Continued) S101833410

Section, Township, Range: 2701E16
 Buried Tank Leak Assessment Date: 07/10/1990
 Initial Report Date: 07/10/1990
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

AA146 SHIVELY TIRE STORE LUST U000196858
 South 925 E CENTRAL N/A
 > 1 WICHITA, KS 67202
 13399 ft.

Site 3 of 3 in cluster AA

Relative:
 Lower

Actual:
 1294 ft.

LUST:
 Facility ID: 11237
 Project Name: SHIVELY TIRE
 Project Number: U208700628
 Project Num Extension: Not reported
 Quarter Fraction of Section: NENW
 Section, Township, Range: 2701E21
 Buried Tank Leak Assessment Date: 01/14/1991
 Initial Report Date: 01/14/1991
 Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

AB147 SEDGWICK CO, COURTHOUSE LUST S103236952
 South 525 N MAIN N/A
 > 1 WICHITA, KS 67203
 13417 ft.

Site 1 of 2 in cluster AB

Relative:
 Lower

Actual:
 1301 ft.

LUST:
 Facility ID: 09094
 Project Name: SEDGWICK CO, COURTHOUSE
 Project Number: U208711974
 Project Num Extension: Not reported
 Quarter Fraction of Section: SESWSESE
 Section, Township, Range: 2701E17
 Buried Tank Leak Assessment Date: 05/29/1998
 Initial Report Date: 05/13/1998
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

AC148 SPURRIER (SUPERIOR?) CHEMICAL CO LUST S103370600
 South 515 N OHIO N/A
 > 1 WICHITA, KS 67214
 13427 ft.

Site 1 of 2 in cluster AC

Relative:
 Lower

Actual:
 1300 ft.

LUST:
 Facility ID: 20238
 Project Name: SPURRIER (SUPERIOR?) CHEMICAL CO
 Project Number: U208712103
 Project Num Extension: Not reported
 Quarter Fraction of Section: SESWSWSE
 Section, Township, Range: 2701E16
 Buried Tank Leak Assessment Date: 09/14/1998
 Initial Report Date: 09/10/1998

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EPA ID Number

SPURRIER (SUPERIOR?) CHEMICAL CO (Continued)

S103370600

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

AB149 South > 1 13487 ft.	SEDGWICK CO. HISTORIC COURTHOU 510 N. MAIN WICHITA, KS 67203	LUST U001111878 N/A
---	---	----------------------------------

Site 2 of 2 in cluster AB

Relative:
Lower

LUST:

Actual: 1301 ft.	Facility ID: 09095 Project Name: SEDGWICK CO, COURTHOUSE-HISTORICAL Project Number: U208711969 Project Num Extension: Not reported Quarter Fraction of Section: SWSESESE Section, Township, Range: 2701E17 Buried Tank Leak Assessment Date: 06/03/1998 Initial Report Date: 06/03/1998
----------------------------	--

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

AC150 South > 1 13501 ft.	ADVANCE PRODUCTS 1199 E CENTRAL WICHITA, KS 67214	LUST S104234822 N/A
---	--	----------------------------------

Site 2 of 2 in cluster AC

Relative:
Lower

LUST:

Actual: 1302 ft.	Facility ID: 81730 Project Name: ADVANCE PRODUCTS Project Number: U208712792 Project Num Extension: Not reported Quarter Fraction of Section: NWNWNWNE Section, Township, Range: 2701E21 Buried Tank Leak Assessment Date: 11/29/1999 Initial Report Date: 11/29/1999
----------------------------	--

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

151 NW > 1 13609 ft.	USD 259, MICHENER ELEM. 2235 W 37TH WICHITA, KS 67204	LUST S101833575 N/A
--------------------------------------	--	----------------------------------

Relative:
Higher

LUST:

Actual: 1318 ft.	Facility ID: 08929 Project Name: USD 259, MICHENER ELEMENTARY Project Number: U208700781 Project Num Extension: Not reported Quarter Fraction of Section: NENWNW Section, Township, Range: 2601E31 Buried Tank Leak Assessment Date: 09/09/1991 Initial Report Date: 04/04/1991
----------------------------	--

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EPA ID Number

154 South > 1 13835 ft.	WICHITA WATER DEPT, CHENEY DAM 455 N MAIN, 8TH FLOOR WICHITA, KS 67202	LUST	S101833542 N/A
---	---	-------------	--------------------------

Relative:
Lower

LUST:

Facility ID: 08598
 Project Name: WICHITA WATER DEPT
 Project Number: U208700159
 Project Num Extension: Not reported
 Quarter Fraction of Section: SWSESE
 Section, Township, Range: 2704W06
 Buried Tank Leak Assessment Date: 05/03/1989
 Initial Report Date: 05/02/1989
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Actual:
1296 ft.

Facility ID: 08598
 Project Name: WICHITA, CENTRAL GARAGE
 Project Number: U208700563
 Project Num Extension: Not reported
 Quarter Fraction of Section: NENWNE
 Section, Township, Range: 2701E20
 Buried Tank Leak Assessment Date: 09/06/1989
 Initial Report Date: 09/06/1989
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 08598
 Project Name: WICHITA, CITY HALL GARAGE
 Project Number: U208700725
 Project Num Extension: Not reported
 Quarter Fraction of Section: NENWNE
 Section, Township, Range: 2701E20
 Buried Tank Leak Assessment Date: 06/12/1991
 Initial Report Date: 06/10/1991
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 08598
 Project Name: WICHITA, CITY OF, VACANT
 Project Number: U208700944
 Project Num Extension: Not reported
 Quarter Fraction of Section: Not reported
 Section, Township, Range: Not reported
 Buried Tank Leak Assessment Date: 05/10/1990
 Initial Report Date: 05/10/1990
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 08598
 Project Name: WICHITA, CITY HALL
 Project Number: U208701301
 Project Num Extension: Not reported
 Quarter Fraction of Section: SWNESESE
 Section, Township, Range: 2701E20
 Buried Tank Leak Assessment Date: 02/09/1994
 Initial Report Date: 02/08/1994

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WICHITA WATER DEPT, CHENEY DAM (Continued)

S101833542

Facility Status: HOLD - A 'Hold' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state but because of circumstances at the site, the state does not require that additional remedial work be performed at this time. As the circumstances may change, the state may then re-assign the site a different status.

AD155
SE
 > 1
 14080 ft.

MAPLE GROVE CEMETERY
1000 N HILLSIDE
WICHITA, KS

LUST S101833502
N/A

Site 1 of 2 in cluster AD

Relative:
 Higher

LUST:

Facility ID: 80053
 Project Name: MAPLE GROVE CEMETERY
 Project Number: U208700656
 Project Num Extension: Not reported
 Quarter Fraction of Section: Not reported
 Section, Township, Range: Not reported
 Buried Tank Leak Assessment Date: 02/25/1991
 Initial Report Date: 02/25/1991
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Actual:
 1338 ft.

AE156
WSW
 > 1
 14101 ft.

WICHITA FIRE STATION #7
2828 W. 13TH ST.
WICHITA, KS 67213

LUST S104938319
N/A

Site 1 of 2 in cluster AE

Relative:
 Lower

LUST:

Facility ID: 09165
 Project Name: FIRE STATION #07, WICHITA
 Project Number: U208700364
 Project Num Extension: Not reported
 Quarter Fraction of Section: Not reported
 Section, Township, Range: Not reported
 Buried Tank Leak Assessment Date: 04/11/1990
 Initial Report Date: 03/05/1990
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Actual:
 1300 ft.

AD157
SE
 > 1
 14130 ft.

MCBRIDE ELECTRIC, INC.
3215 E 9TH
WICHITA, KS 67208

LUST S102406702
N/A

Site 2 of 2 in cluster AD

Relative:
 Higher

LUST:

Facility ID: 28758
 Project Name: MCBRIDE ELECTRIC
 Project Number: U208700371
 Project Num Extension: Not reported
 Quarter Fraction of Section: NWNWNWSW
 Section, Township, Range: 2701E14
 Buried Tank Leak Assessment Date: 03/29/1990
 Initial Report Date: 03/28/1990

Actual:
 1337 ft.

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

MCBRIDE ELECTRIC, INC. (Continued)

S102406702

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

AF158
 South
 > 1
 14135 ft.

YMCA, WICHITA
402 N MARKET
WICHITA, KS 67202

LUST S101833878
N/A

Site 1 of 2 in cluster AF

Relative:
Lower

LUST:

Facility ID: 29692
 Project Name: YMCA, WICHITA
 Project Number: U208701327
 Project Num Extension: Not reported
 Quarter Fraction of Section: SENENENE
 Section, Township, Range: 2701E20
 Buried Tank Leak Assessment Date: 04/25/1994
 Initial Report Date: 04/23/1994

Actual:
1287 ft.

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

AF159
 South
 > 1
 14149 ft.

US FEDERAL COURT HOUSE
401 N MARKET
WICHITA, KS 67201

LUST S101833692
N/A

Site 2 of 2 in cluster AF

Relative:
Lower

LUST:

Facility ID: 26303
 Project Name: US FEDERAL COURTHOUSE
 Project Number: U208711417
 Project Num Extension: Not reported
 Quarter Fraction of Section: SWNENENE
 Section, Township, Range: 2701E20
 Buried Tank Leak Assessment Date: 03/05/1997
 Initial Report Date: 03/05/1997

Actual:
1288 ft.

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 28203
 Project Name: US POSTAL SERV, WICHITA
 Project Number: U208700986
 Project Num Extension: Not reported
 Quarter Fraction of Section: NENENWNE
 Section, Township, Range: 2701E20
 Buried Tank Leak Assessment Date: 07/22/1992
 Initial Report Date: 05/10/1991
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 28203
 Project Name: US POSTAL SERV, DOWNTOWN OFC
 Project Number: U208712392
 Project Num Extension: Not reported
 Quarter Fraction of Section: NWNWNWSE
 Section, Township, Range: 2701E20
 Buried Tank Leak Assessment Date: 02/16/1999

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

US FEDERAL COURT HOUSE (Continued)

S101833692

Initial Report Date: 02/16/1999
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

AE160 AMOCO #5363, WICHITA LUST S101833855
WSW 2849 W 13TH ST N/A
> 1 WICHITA, KS 67203
14149 ft.

Site 2 of 2 in cluster AE

Relative:
Lower

LUST:

Facility ID: 23247
Project Name: AMOCO #5363, WICHITA
Project Number: U208701275
Project Num Extension: Not reported
Quarter Fraction of Section: NWNENE
Section, Township, Range: 2701W13
Buried Tank Leak Assessment Date: 02/07/1994
Initial Report Date: 08/27/1993
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

AG161 KG&E, WICHITA SERVICE BLDG LUST S101833259
SSE 1900 E CENTRAL N/A
> 1 WICHITA, KS 67201
14213 ft.

Site 1 of 2 in cluster AG

Relative:
Lower

LUST:

Facility ID: 06772
Project Name: KG&E, WICHITA SERV
Project Number: U208711274
Project Num Extension: Not reported
Quarter Fraction of Section: SESESWSW
Section, Township, Range: 2701E15
Buried Tank Leak Assessment Date: 05/13/1994
Initial Report Date: 03/22/1994
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 06772
Project Name: KG&E, WICHITA SERVICE BLDG
Project Number: U208700191
Project Num Extension: Not reported
Quarter Fraction of Section: SESESWSW
Section, Township, Range: 2701E15
Buried Tank Leak Assessment Date: 11/25/1992
Initial Report Date: 11/09/1990
Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EPA ID Number

AG162 SSE > 1 14350 ft.	COASTAL MART #9177 2012 E CENTRAL WICHITA, KS 67214 Site 2 of 2 in cluster AG	LUST	U000871485 N/A
--	---	-------------	--------------------------

Relative:
Lower

Actual:
 1308 ft.

LUST:

Facility ID: 07229

Project Name: COASTAL MART #9177

Project Number: U208710860

Project Num Extension: Not reported

Quarter Fraction of Section: SWSWSESW

Section, Township, Range: 2701E15

Buried Tank Leak Assessment Date: 03/18/1996

Initial Report Date: 02/22/1996

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

AH163 South > 1 14421 ft.	SYD WERBIN 355 N WASHINGTON WICHITA, KS 67214 Site 1 of 2 in cluster AH	LUST	S102406874 N/A
--	---	-------------	--------------------------

Relative:
Lower

Actual:
 1297 ft.

LUST:

Facility ID: 81332

Project Name: SYD WERBIN

Project Number: U208710612

Project Num Extension: Not reported

Quarter Fraction of Section: SENENW

Section, Township, Range: 2701E21

Buried Tank Leak Assessment Date: 10/20/1995

Initial Report Date: 10/16/1995

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 81332

Project Name: BURKLUND PROPERTY

Project Number: U407510598

Project Num Extension: Not reported

Quarter Fraction of Section: SWSENE

Section, Township, Range: 0707E23

Buried Tank Leak Assessment Date: 10/13/1995

Initial Report Date: 09/14/1995

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

AI164 South > 1 14504 ft.	FLASHER CO. 333 N ROCK ISLAND WICHITA, KS 67213 Site 1 of 2 in cluster AI	LUST	S101833532 N/A
--	---	-------------	--------------------------

Relative:
Lower

Actual:
 1293 ft.

LUST:

Facility ID: 80075

Project Name: FLASHER CO

Project Number: U208700710

Project Num Extension: Not reported

Quarter Fraction of Section: SWNENW

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

Site

Database(s)

EDR ID Number
 EPA ID Number

FLASHER CO. (Continued)

S101833532

Section, Township, Range: 2701E21
 Buried Tank Leak Assessment Date: 06/13/1991
 Initial Report Date: 06/13/1991
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

AH165
South
> 1
14513 ft.

ARMORED SERVICES, INC.
342 N WASHINGTON
WICHITA, KS 67202

LUST S102406656
N/A

Site 2 of 2 in cluster AH

Relative:
Lower

LUST:

Facility ID: 23853
 Project Name: ARMORED SERVICES
 Project Number: U208700163
 Project Num Extension: Not reported
 Quarter Fraction of Section: SWNWNE
 Section, Township, Range: 2701E21
 Buried Tank Leak Assessment Date: 05/16/1989
 Initial Report Date: 05/16/1989
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Actual:
1295 ft.

AJ166
SSW
> 1
14673 ft.

WICHITA, CITY OF, WATER
1701 SIMS PARK
WICHITA, KS 67203

LUST S103236703
N/A

Site 1 of 2 in cluster AJ

Relative:
Lower

LUST:

Facility ID: 09033
 Project Name: WICHITA, CITY OF, WATER
 Project Number: U208700136
 Project Num Extension: Not reported
 Quarter Fraction of Section: NE
 Section, Township, Range: 2701E19
 Buried Tank Leak Assessment Date: 02/27/1989
 Initial Report Date: 02/17/1989
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Actual:
1267 ft.

Facility ID: 09033
 Project Name: WICHITA, CITY OF, MAINS & SERVICE
 Project Number: U208700249
 Project Num Extension: Not reported
 Quarter Fraction of Section: NE
 Section, Township, Range: 2701E19
 Buried Tank Leak Assessment Date: 10/20/1989
 Initial Report Date: 10/05/1989
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

Site

Database(s) EDR ID Number
 EPA ID Number

AI167 **ROSS SERVICE CENTER**
South **825 EAST SECOND STREET**
> 1 **WICHITA, KS 67202**
14725 ft.

LUST **U001112153**
 N/A

Site 2 of 2 in cluster AI

Relative:
Lower

LUST:

Facility ID: 26494
 Project Name: ROSS SERVICE CENTER (NORTH SIDE)
 Project Number: U208700202
 Project Num Extension: Not reported
 Quarter Fraction of Section: Not reported
 Section, Township, Range: Not reported
 Buried Tank Leak Assessment Date: 12/11/1989
 Initial Report Date: 12/11/1989
 Facility Status: **MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.**

AJ168 **WICHITA ART MUSEUM**
SSW **619 N STACKMAN**
> 1 **WICHITA, KS 67202**
14753 ft.

LUST **S104938318**
 N/A

Site 2 of 2 in cluster AJ

Relative:
Lower

LUST:

Facility ID: 09180
 Project Name: WICHITA ART MUSEUM
 Project Number: U208700220
 Project Num Extension: Not reported
 Quarter Fraction of Section: Not reported
 Section, Township, Range: Not reported
 Buried Tank Leak Assessment Date: 09/06/1989
 Initial Report Date: 09/06/1989
 Facility Status: **CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.**

169 **AUTOHOUSE STUTTGART, INC.**
South **1106 E. 2ND ST.**
> 1 **WICHITA, KS 67214**
14794 ft.

LUST **U000198719**
 N/A

Relative:
Lower

LUST:

Facility ID: 28161
 Project Name: AUTOHOUSE STUTTGART INC
 Project Number: U208712998
 Project Num Extension: Not reported
 Quarter Fraction of Section: SENWSWNE
 Section, Township, Range: 2701E21
 Buried Tank Leak Assessment Date: 11/07/2000
 Initial Report Date: 10/31/2000
 Facility Status: **CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.**

MAP FINDINGS

Map ID	Direction	Distance	Distance (ft.)	Elevation	Site	Database(s)	EDR ID Number	EPA ID Number
AK170	SSW	> 1	14864 ft.		THE LAW COMPANY INC 345 RIVERVIEW WICHITA, KS 67203 Site 1 of 2 in cluster AK LUST: Facility ID: 28251 Project Name: LAW COMPANY (THE) Project Number: U208701104 Project Num Extension: Not reported Quarter Fraction of Section: NCSWNWNE Section, Township, Range: 2701E20 Buried Tank Leak Assessment Date: 02/05/1993 Initial Report Date: 02/05/1993 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.	LUST	S101833760	N/A
171	WSW	> 1	14946 ft.		FOAMY CAR WASH 13TH / ST PAUL WICHITA, KS 67213 LUST: Facility ID: 80077 Project Name: FOAMY CAR WASH Project Number: U208700331 Project Num Extension: Not reported Quarter Fraction of Section: Not reported Section, Township, Range: Not reported Buried Tank Leak Assessment Date: 02/06/1990 Initial Report Date: 02/06/1990 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.	LUST	S101833339	N/A
172	SSE	> 1	14998 ft.		EUROPEAN CAR COMPANY 1510 E. 2ND WICHITA, KS 67214 LUST: Facility ID: 30179 Project Name: EUROPEAN CAR CO Project Number: U208713105 Project Num Extension: Not reported Quarter Fraction of Section: NWNWSENE Section, Township, Range: 2701E21 Buried Tank Leak Assessment Date: 06/08/2001 Initial Report Date: 06/07/2001 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.	LUST	U003790440	N/A

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

173 NNE > 1 15019 ft.	RAY, BILL RESIDENCE 4821 N HYDRAULIC WICHITA, KS 67219	LUST	S101901127 N/A
---	---	-------------	---------------------------------

Relative: Higher

Actual: 1361 ft.

LUST:

Facility ID:	81157
Project Name:	RAY, BILL
Project Number:	U208710079
Project Num Extension:	Not reported
Quarter Fraction of Section:	SESENESE
Section, Township, Range:	2601E21
Buried Tank Leak Assessment Date:	12/27/1993
Initial Report Date:	12/27/1993
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

174 South > 1 15029 ft.	SHIRKMERE APTS. 256 N TOPEKA WICHITA, KS 67202	LUST	S102406729 N/A
---	---	-------------	---------------------------------

Relative: Lower

Actual: 1300 ft.

LUST:

Facility ID:	80030
Project Name:	SHIRKMERE APTS
Project Number:	U208700453
Project Num Extension:	Not reported
Quarter Fraction of Section:	NWSWNW
Section, Township, Range:	2701E21
Buried Tank Leak Assessment Date:	06/26/1990
Initial Report Date:	06/15/1990
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

AK175 SSW > 1 15034 ft.	GREENWAY MANOR 315 RIVERVIEW WICHITA, KS 67203	LUST	S101833617 N/A
---	---	-------------	---------------------------------

Relative: Lower

Actual: 1300 ft.

Site 2 of 2 in cluster AK

LUST:

Facility ID:	29261
Project Name:	GREENWAY MANOR
Project Number:	U208700852
Project Num Extension:	Not reported
Quarter Fraction of Section:	SWNENE
Section, Township, Range:	2701E17
Buried Tank Leak Assessment Date:	01/07/1992
Initial Report Date:	01/07/1992
Facility Status:	CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EPA ID Number
			EDR ID Number

AL176 South > 1 15066 ft.	ROSS SERVICE CENTER 248 N ROCK ISLAND WICHITA, KS 67202	LUST	U000196843 N/A
---	--	------	-------------------

Site 1 of 3 in cluster AL

Relative: Lower Actual: 1292 ft.	LUST: Facility ID: 10896 Project Name: ROSS SERVICE CENTER (SOUTH SIDE) Project Number: U208712925 Project Num Extension: Not reported Quarter Fraction of Section: Not reported Section, Township, Range: Not reported Buried Tank Leak Assessment Date: 05/12/2000 Initial Report Date: 05/01/2000 Facility Status: HOLD - A 'Hold' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state but because of circumstances at the site, the state does not require that additional remedial work be performed at this time. As the circumstances may change, the state may then re-assign the site a different status.
---	--

177 ENE > 1 15087 ft.	KOCH BUSINESS SOLUTIONS LP 4111 E 37TH ST N (A) WICHITA, KS 67220	LUST	1000238223 67220KCHNG41
--------------------------------	--	------	----------------------------

Relative: Higher Actual: 1377 ft.	LUST: Facility ID: 28375 Project Name: KOCH INDUSTRIES Project Number: U208711626 Project Num Extension: Not reported Quarter Fraction of Section: NENENWNE Section, Township, Range: 2601E35 Buried Tank Leak Assessment Date: 07/29/1997 Initial Report Date: 07/01/1997 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.
--	--

	Facility ID: 28375 Project Name: KOCH INDUSTRIES Project Number: U208711627 Project Num Extension: Not reported Quarter Fraction of Section: NWNWNE Section, Township, Range: 2601E35 Buried Tank Leak Assessment Date: 07/29/1997 Initial Report Date: 07/03/1997 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.
--	---

178 WSW > 1 15099 ft.	KENNEDY TIRE INC 3250 W 13TH WICHITA, KS 67213	LUST	1001087664 KSR000003335
--------------------------------	---	------	----------------------------

Relative: Lower Actual: 1306 ft.	LUST: Facility ID: 00420 Project Name: KENNEDY TIRE Project Number: U208700222 Project Num Extension: Not reported Quarter Fraction of Section: Not reported Section, Township, Range: Not reported
---	---

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

KENNEDY TIRE INC (Continued)

1001087664

Buried Tank Leak Assessment Date: 01/05/1990
Initial Report Date: 11/30/1989
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

179
SSE
> 1
15130 ft.

CAR CARE
1630 E SECOND STREET
WICHITA, KS 67214

LUST U000873965
N/A

Relative:
Lower

LUST:

Facility ID: 28227
Project Name: CAR CARE
Project Number: U208701307
Project Num Extension: Not reported
Quarter Fraction of Section: SENENE
Section, Township, Range: 2701E21
Buried Tank Leak Assessment Date: 04/07/1994
Initial Report Date: 03/31/1994

Actual:
1292 ft.

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

AL180
South
> 1
15184 ft.

FINA STATION
233 N MOSLEY
WICHITA, KS 67202

LUST S103370343
N/A

Relative:
Lower

Site 2 of 3 in cluster AL

LUST:

Facility ID: 29031
Project Name: FINA STATION
Project Number: U208711290
Project Num Extension: Not reported
Quarter Fraction of Section: NESENW
Section, Township, Range: 2701E21
Buried Tank Leak Assessment Date: 08/17/1993
Initial Report Date: 08/16/1993

Actual:
1296 ft.

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 29031
Project Name: MERCHANTS OIL
Project Number: U208700887
Project Num Extension: Not reported
Quarter Fraction of Section: SENW
Section, Township, Range: 2701E21
Buried Tank Leak Assessment Date: 02/25/1992
Initial Report Date: 10/17/1991

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

AM181 South > 1 15291 ft.	MISCO INDUSTRIES, INC 223 N BROADWAY WICHITA, KS 67202 Site 1 of 2 in cluster AM	LUST	S101833676 N/A
Relative: Lower	LUST: Facility ID: 80062 Project Name: MISCO INDUSTRIES Project Number: U208700966 Project Num Extension: A Quarter Fraction of Section: NESENE Section, Township, Range: 2701E20 Buried Tank Leak Assessment Date: 06/26/1992 Initial Report Date: 06/12/1992 Facility Status: HOLD - A 'Hold' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state but because of circumstances at the site, the state does not require that additional remedial work be performed at this time. As the circumstances may change, the state may then re-assign the site a different status.		

AM182 South > 1 15291 ft.	MISCO INDUSTRIES 223 N BROADWAY WICHITA, KS 67203 Site 2 of 2 in cluster AM	LUST	S101833677 N/A
Relative: Lower	LUST: Facility ID: 80061 Project Name: MISCO INDUSTRIES Project Number: U208700966 Project Num Extension: B Quarter Fraction of Section: SWNWSWNW Section, Township, Range: 2701E21 Buried Tank Leak Assessment Date: 06/23/1992 Initial Report Date: 06/23/1992 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.		

AN183 SE > 1 15329 ft.	WICHITA CHILDRENS HOME 810 N HOLYOKE WICHITA, KS 67208 Site 1 of 2 in cluster AN	LUST	S101833578 N/A
Relative: Higher	LUST: Facility ID: 29313 Project Name: WICHITA CHILDRENS HOME, WICHITA, 810 N H Project Number: U208700784 Project Num Extension: Not reported Quarter Fraction of Section: SENWSW Section, Township, Range: 2701E14 Buried Tank Leak Assessment Date: 08/30/1991 Initial Report Date: 10/29/1991 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.		

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

Site

Database(s) EDR ID Number
 EPA ID Number

AL184
 South
 > 1
 15386 ft.

MEAD
WICHITA, KS

LUST **S101901098**
 N/A

Site 3 of 3 in cluster AL

Relative:
Lower

Actual:
1300 ft.

LUST:
 Facility ID: 81122
 Project Name: COLEMAN PLANT 3 (OLD)
 Project Number: U208710045
 Project Num Extension: Not reported
 Quarter Fraction of Section: NWSENW
 Section, Township, Range: 2701E21
 Buried Tank Leak Assessment Date: 12/08/1993
 Initial Report Date: 11/30/1993
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 81122
 Project Name: COLEMAN PLANT 3 (OLD)
 Project Number: U208710045
 Project Num Extension: B
 Quarter Fraction of Section: NWSENW
 Section, Township, Range: 2701E21
 Buried Tank Leak Assessment Date: 01/27/1994
 Initial Report Date: 01/19/1994
 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

185
 South
 > 1
 15391 ft.

SOUTHWEST PAPER
923 E 1ST (/ WASHINGTON)
WICHITA, KS 67202

LUST **S102843872**
 N/A

Relative:
Lower

Actual:
1294 ft.

LUST:
 Facility ID: 28582
 Project Name: SOUTHWEST PAPER (FORMER TYSONS APCO)
 Project Number: U208700320
 Project Num Extension: Not reported
 Quarter Fraction of Section: NESESENW
 Section, Township, Range: 2701E21
 Buried Tank Leak Assessment Date: 01/12/1990
 Initial Report Date: 01/10/1990
 Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

186
 SE
 > 1
 15400 ft.

MCDONALD GOLF COURSE
1026 N ROOSEVELT
WICHITA, KS 67208

LUST **S101833334**
 N/A

Relative:
Higher

Actual:
1388 ft.

LUST:
 Facility ID: 25651
 Project Name: MCDONALD GOLF COURSE
 Project Number: U208700315
 Project Num Extension: A
 Quarter Fraction of Section: SESENW
 Section, Township, Range: 2701E14
 Buried Tank Leak Assessment Date: 01/04/1990

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

MCDONALD GOLF COURSE (Continued)

S101833334

Initial Report Date: 01/03/1990
Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 25651
Project Name: MCDONALD GOLF COURSE, MAINTENANCE
Project Number: U208700315
Project Num Extension: B
Quarter Fraction of Section: SESENW
Section, Township, Range: 2701E14
Buried Tank Leak Assessment Date: 05/03/1991
Initial Report Date: 05/02/1991

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

Facility ID: 25651
Project Name: CLAPP GOLF COURSE
Project Number: U208700729
Project Num Extension: Not reported
Quarter Fraction of Section: NWSWNE
Section, Township, Range: 2701E35
Buried Tank Leak Assessment Date: 05/07/1991
Initial Report Date: 05/07/1991

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

AN187
SE
> 1
15431 ft.

WICHITA CLININC BLDG
3311 E MURDOCK
WICHITA, KS 67208

LUST S102689601
N/A

Site 2 of 2 in cluster AN

Relative:
Higher

Actual:
1350 ft.

LUST:
Facility ID: 07820
Project Name: WICHITA CLINIC BLDG
Project Number: U208711662
Project Num Extension: Not reported
Quarter Fraction of Section: NWNESWSW
Section, Township, Range: 2701E14
Buried Tank Leak Assessment Date: 03/20/1997
Initial Report Date: 03/19/1997

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

188
ESE
> 1
15485 ft.

WHITE CHAPEL
1806 N OLIVER
WICHITA, KS 67208

LUST S101833608
N/A

Relative:
Higher

Actual:
1408 ft.

LUST:
Facility ID: 28469
Project Name: WHITE CHAPPEL
Project Number: U208700840
Project Num Extension: Not reported
Quarter Fraction of Section: SESENW
Section, Township, Range: 2701E12
Buried Tank Leak Assessment Date: 12/16/1991
Initial Report Date: 12/16/1991

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

WHITE CHAPEL (Continued)

S101833608

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

AO189
 East
 > 1
 15536 ft.

QUIK TRIP #342
5001 E 21ST
WICHITA, KS 67208

LUST S101833894
N/A

Site 1 of 2 in cluster AO

Relative:
 Higher

LUST:

Facility ID: 07276
 Project Name: QUIK TRIP #342
 Project Number: U208701384
 Project Num Extension: Not reported
 Quarter Fraction of Section: NWNWNWNW
 Section, Township, Range: 2701E12
 Buried Tank Leak Assessment Date: 11/03/1994
 Initial Report Date: 05/12/1994

Actual:
 1405 ft.

Facility Status: MONITOR - A 'Monitor' status indicates that there exists levels of contamination at the site that are greater than cleanup levels set by the state and that the work required by the state to remain in compliance is the routine monitoring of existing monitoring points.

190
 South
 > 1
 15546 ft.

UNITED ROOFING & BUILDING SUPP
1321 E FIRST STREET
WICHITA, KS 67214

LUST U000198587
N/A

Relative:
 Lower

LUST:

Facility ID: 27882
 Project Name: UNITED ROOFING SUPPLY
 Project Number: U208711390
 Project Num Extension: Not reported
 Quarter Fraction of Section: NESESWNE
 Section, Township, Range: 2701E21
 Buried Tank Leak Assessment Date: 02/06/1997
 Initial Report Date: 02/05/1997

Actual:
 1292 ft.

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

AO191
 East
 > 1
 15569 ft.

KMART, #7117
5010 E 21ST N
WICHITA, KS 67208

LUST S102406786
N/A

Site 2 of 2 in cluster AO

Relative:
 Higher

LUST:

Facility ID: 26430
 Project Name: KMART #7117
 Project Number: U208700894
 Project Num Extension: Not reported
 Quarter Fraction of Section: SESW
 Section, Township, Range: 2701E01
 Buried Tank Leak Assessment Date: 02/10/1992
 Initial Report Date: 05/31/1990

Actual:
 1404 ft.

Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.

MAP FINDINGS

Map ID			
Direction			
Distance			
Distance (ft.)			
Elevation	Site	Database(s)	EDR ID Number EPA ID Number

KMART, #7117 (Continued)

S102406786

<p>192 SSW > 1 15580 ft.</p>	<p>MCKAY OIL CO. 369 MCLEAN BLVD NW WICHITA, KS 67203</p>	<p>LUST</p>	<p>S101833416 N/A</p>
---	--	-------------	---------------------------

<p>Relative: Lower</p>	<p>LUST: Facility ID: 02751 Project Name: MCKAY OIL CO Project Number: U208700477 Project Num Extension: Not reported Quarter Fraction of Section: NWNW Section, Township, Range: 2701E20 Buried Tank Leak Assessment Date: 07/25/1990 Initial Report Date: 07/25/1990 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.</p>		
----------------------------	---	--	--

<p>193 South > 1 15740 ft.</p>	<p>SOUTHWEST PAPER, FORMER 150 N MOSLEY WICHITA, KS 67202</p>	<p>LUST</p>	<p>S102406820 N/A</p>
---	--	-------------	---------------------------

<p>Relative: Lower</p>	<p>LUST: Facility ID: 80032 Project Name: SOUTHWEST PAPER, FORMER Project Number: U208701135 Project Num Extension: Not reported Quarter Fraction of Section: NESESENW Section, Township, Range: 2701E21 Buried Tank Leak Assessment Date: 04/09/1993 Initial Report Date: 03/18/1993 Facility Status: CLOSED - a 'Closed' status indicates that according to the data available, levels of contamination at the site do not exceed cleanup levels set by the state.</p>		
----------------------------	--	--	--

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
PRATT	S101832528	H-30 DRILLING, INC.	N HWY 281	67202	LUST
WICHITA	S104818337	QUIK TRIP #325	4703 E 13TH (DELLROSE DR)	67208	LUST
WICHITA	S104402426	WALLY'S AUTO	53RD / N BROADWAY (SE CORNER)	67219	LUST
WICHITA	S104938502	FORMER SERVICE STATION (PIZZA H)	1708 E PAWNEE (HYDRAULIC)		LUST

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Elapsed ASTM days: Provides confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

FEDERAL ASTM STANDARD RECORDS

FEDERAL ASTM SUPPLEMENTAL RECORDS

BRS: Biennial Reporting System

Source: EPA/NTIS

Telephone: 800-424-9346

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/01/01

Database Release Frequency: Biennially

Date of Last EDR Contact: 10/01/03

Date of Next Scheduled EDR Contact: 12/15/03

STORMWATER: Storm Water General Permits

Source: Environmental Protection Agency

Telephone: 202 564-0746

A listing of all facilities with Storm Water General Permits.

Date of Government Version: N/A

Database Release Frequency: Quarterly

Date of Last EDR Contact: N/A

Date of Next Scheduled EDR Contact: N/A

US BROWNFIELDS: A Listing of Brownfields Sites

Source: Environmental Protection Agency

Telephone: 202-566-2777

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become BCRLF cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 07/15/03

Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 09/15/03

Date of Next Scheduled EDR Contact: 12/15/03

RMP: Risk Management Plans

Source: Environmental Protection Agency

Telephone: 202-564-8600

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: N/A
Database Release Frequency: N/A

Date of Last EDR Contact: N/A
Date of Next Scheduled EDR Contact: N/A

STATE OF KANSAS ASTM STANDARD RECORDS

LUST: Leaking Underground Storage Tank Data

Source: Department of Health and Environment
Telephone: 785-296-1685

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 11/04/03
Date Made Active at EDR: 11/21/03
Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 11/04/03
Elapsed ASTM days: 17
Date of Last EDR Contact: 09/30/03

STATE OF KANSAS ASTM SUPPLEMENTAL RECORDS

AOCONCERN: Area of Concern

Source: Department of Environmental Health
Telephone: 315-268-8351

The City of Wichita has taken the lead for the investigation and remediation efforts with the Kansas Department of Health & Environment, Bureau of Remediation. The primary contaminants of concern are chlorinated solvents and their degradation products.

Date of Government Version: N/A
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 04/19/02
Date of Next Scheduled EDR Contact: N/A

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data

Source: PennWell Corporation
Telephone: (800) 823-6277

This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc.
Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Nursing Homes

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 from the U.S. Fish and Wildlife Service.

STREET AND ADDRESS INFORMATION

© 2003 Geographic Data Technology, Inc., Rel. 07/2003. This product contains proprietary and confidential property of Geographic Data Technology, Inc. Unauthorized use, including copying for other than testing and standard backup procedures, of this product is expressly prohibited.